



report date: 2024-03-29

General information

Make	ABARTH
Model	500 ABARTH
Colour	Red
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	135 BHP
Max. torque	180 Nm at 2.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	155 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-07-09
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-13
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	39
Total items failed	12

MOT #17 2024-03-14 09:59

MOT test number 534234181328

Result ✓ Passed

Next expiry date 2025-03-13

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Front Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Service brake fluctuating, but not excessively offside & nearside (1.2.1 (e))

MOT #16 2023-01-25 16:40

MOT test number 291953009080

Result ✓ Passed

MOT #15 2022-04-09 10:33

MOT test number 794765105354

Result ✓ Passed

**MOT #14** 2022-03-23 15:31**MOT test number** 787657411576**Result** ✗ Failed**Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Oil leak**MOT #13** 2021-07-01 13:35**MOT test number** 553977846581**Result** ✓ Passed**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))**Advice** Exhaust flexi section slightly damaged**MOT #12** 2021-06-29 11:26**MOT test number** 804312519845**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))**Fail** Reversing lamp inoperative (4.6.1 (a))**Advice** Exhaust flexi section slightly damaged**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**MOT #11** 2020-07-08 11:11**MOT test number** 777152981317**Result** ✓ Passed



MOT #10	2020-07-06 14:35
MOT test number	393026905254
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive gearbox (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #9	2019-04-15 08:35
MOT test number	709825270787
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear hand brake cable mountings deteriorated

**MOT #8** 2018-04-07 11:38**MOT test number** 302955342555**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Front Tyre worn close to the legal limit inside edge (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Rear Shock absorber has a slightly worn bush upper bush (2.7.4)**Advice** Offside Rear wheel bearing has slight play (2.6.2)**Advice** Offside Front Tyre worn close to the legal limit inside edge (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #7** 2017-03-29 09:06**MOT test number** 730729942906**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2016-04-06 11:41**MOT test number** 463367765881**Result** ✓ Passed

**MOT #5** 2016-04-06 08:39**MOT test number** 126659020869**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front brake excessively fluctuating (3.7.B.3)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2015-04-17 11:35**MOT test number** 757207405131**Result** ✓ Passed**MOT #3** 2015-04-06 15:50**MOT test number** 618456895000**Result** ✗ Failed**Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)**MOT #2** 2014-04-08 10:16**MOT test number** 906848994054**Result** ✓ Passed



MOT #1

2014-04-03 15:42

MOT test number

919313894096

Result		✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail	Offside Rear wheel bearing rough when rotated (2.6.1)	
Advice	Nearside front brake fluctuating, but not excessively (3.7.B.3)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail	Driver's door cannot be opened from outside the vehicle (6.2.B.1b)	
Advice	Offside front brake fluctuating, but not excessively (3.7.B.3)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
13 March 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this ABARTH? How many owners did this ABARTH have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this ABARTH had different number plates.

Number of plates	1
Current registration	SB60KUE
Plate since	2024-03-29
Current registration	SB60KUE
Plate since	2024-03-29

More info >



Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled. If not, and you buy this ABARTH then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this ABARTH is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-12-29
Last registration	2024-03-14
Complete history	See info



Registration #1	2010-12-29	24 mi
Registration #2	2014-04-03	19.088 mi
Registration #3	2014-04-08	19.090 mi
Registration #4	2015-04-06	21.788 mi
Registration #5	2015-04-17	21.788 mi
Registration #6	2016-04-06	23.780 mi
Registration #7	2016-04-06	23.780 mi
Registration #8	2017-03-29	24.385 mi
Registration #9	2018-04-07	40.976 mi
Registration #10	2019-04-15	56.213 mi
Registration #11	2020-04-07	71.377 mi
Registration #12	2021-04-07	86.541 mi
Registration #13	2022-04-07	101.705 mi
Registration #14	2023-04-07	116.869 mi
Registration #15	2024-03-14	132.033 mi
Registration #16		
Registration #17		
Registration #18		
Registration #19		

More info >



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3657 mm
Wheel base	2300 mm
Kerb weight	1035 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1491003