



report date: 2024-03-29

General information

Make	MINI
Model	COOPER D
Colour	Black
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B







Internet history

Entry 1

Date	2021-05-28
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-05
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	17
Total items failed	9

MOT #9	2023-05-06 12:00
MOT test number	588805305561
Result	✓ Passed
Next expiry date	2024-05-05
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #8	2023-05-06 11:59
MOT test number	772146748385
Result	✗ Failed
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #7	2020-08-05 15:35
MOT test number	157139110516
Result	✓ Passed

MOT #6	2017-08-15 13:13
MOT test number	339761492707
Result	✓ Passed
Advice	Front brake pads low

**MOT #5** 2016-08-15 13:49**MOT test number** 831762397101**Result** ✓ Passed**MOT #4** 2015-10-08 16:15**MOT test number** 999510362235**Result** ✓ Passed**MOT #3** 2015-10-08 10:39**MOT test number** 120220772119**Result** ✗ Failed**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2014-05-02 17:06**MOT test number** 905812924125**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in offside rear tyre**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #1

2014-05-02 15:52

MOT test number

217032724172

Result		✗ Failed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Wipers split	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	
Fail	Nearside Headlamp aim too high (1.8)	
Fail	Offside Registration plate lamp not working (1.1.C.1d)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Notice	Nail in offside rear tyre	
Advice	Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Fail	Offside Front position lamp(s) not working (1.1.A.3b)	
Fail	Offside Headlamp aim too high (1.8)	
Notice	Under-trays fitted obscuring some underside components	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
5 May 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	5 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	GV60AEA
Plate since	2024-03-29
Current registration	GV60AEA
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2010-12-13
Last registration	2023-05-06
Complete history	See info



Registration #1	2010-12-13	18 mi
Registration #2	2014-05-02	43.962 mi
Registration #3	2014-05-02	43.962 mi
Registration #4	2015-10-08	59.616 mi
Registration #5	2015-10-08	59.616 mi
Registration #6	2016-08-15	74.121 mi
Registration #7	2019-05-29	95.277 mi
Registration #8	2019-05-29	95.277 mi
Registration #9	2019-05-29	95.277 mi
Registration #10	2019-05-29	95.277 mi
Registration #11	2023-05-06	118.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1200 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	70077520