





report date: 2024-03-28

#### General information

Make	CITROEN
Model	DS3 E-HDI FLAIR ETG6
Colour	White
Year of manufacture	2015
Top speed	114 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	91 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-10-16

Pictures 22

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

# MOT history

MOT expiry date	2024-09-28
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	17
Total items failed	4

MOT #9	2023-09-29 07:09
MOT test number	560715742502
Result	✓ Passed
Next expiry date	2024-09-28
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #8	2023-09-28 10:40
MOT test number	740305885530
Result	<b>×</b> Failed
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no lingress of dirt (6.1.7 (g) (ii))	onger prevents the
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamp (4.7.1 (b) (i))	os or light sources
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

 MOT #7
 2022-09-26 12:01

 MOT test number
 490576100147

 Result
 ✓ Passed

 Advice
 Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #6** 2022-09-22 08:56 **MOT** test number 276710434176 Result × Failed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

 MOT #5
 2021-09-16 11:58

 MOT test number
 369602479871

 Result
 ✓ Passed

MOT #4

MOT test number

Result

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

 MOT #3
 2019-12-04 11:40

 MOT test number
 353377711500

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge. (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge. (5.2.3 (e))

Advice Brake pad(s) wearing thin Both side front. (1.1.13 (a) (ii))

MOT #1

MOT test number

402571058211

Result

Advice Both rear brakes slightly binding

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax expired: 4 November 2023

# ✓ MOT

Expires: 28 September 2024

Tax status Expired at 4 November 2023

Days left 178 days too late

MOT expiry date 28 September 2024

Full MOT history See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

$\sim$	wner	ъi	ct	<b>1</b>
$ \cup$	wner		รเบ	IΙV

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
HARMAN CONTRACTOR CONT	
THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NE ZIN
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-01-21
Last registration	2023-09-29
Complete history	See info



Registration #1	2015-01-21	21 mi
Registration #2	2017-11-27	60.904 mi
Registration #3	2018-11-06	68.238 mi
Registration #4	2019-12-04	71.562 mi
Registration #5	2020-09-28	75.623 mi
Registration #6	2021-09-16	80.791 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		10.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1946 mm
Height	1540 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1055 kg
Max. allowed weight	1605 kg

## Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	JBFN0073270

CarCheck.co.uk page 12/12