





General information

Make	AUDI
Model	TT QUATTRO (225BHP)
Colour	Turquoise
Year of manufacture	2002
Top speed	151 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	225 BHP	0 < 101 A
Max. torque	280 Nm at 2.200 rpm	101 - 120 ^B _C
Engine capacity	1.781 cc	121 - 140 P
Cylinders	4	141 - 165 E
Fuel type	Petrol	166 - 185
Consumption city	23.0 mpg	186 - 225 J
Consumption extra urban	38.7 mpg	225+ L
Consumption combined	30.7 mpg	
CO2 emission	226 g/km	
CO2 label	L	

ELL





Internet history		
Entry 1		
Date	2021-01-28	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-27
MOT pass rate	90 %
MOT passed	18
Failed MOT tests	2
Total advice items	11
Total items failed	11

MOT #20 20	23-07-28 13:43
MOT test number	288046446237
Result	🗸 Passed
Next expiry date	2024-07-27
Minor Offside Side repeater insecure (4.4.1 (c) (i))	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	





MOT #19	2023-07-26 10:21
MOT test n	1000 See State St
Result	× Failed
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail Ex	haust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail An	ti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Fail Ex	haust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Minor	Offside Side repeater insecure (4.4.1 (c) (i))
Fail Off	fside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail Ex	haust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
	fside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5
(a))	
(a))	haust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2
	ectronic stability control warning lamp indicates a fault (7.12 (e))

MOT #18	2021-01-20 12:58
MOT test number	925067965177
Result	✓ Passed

MOT #17	2020-06-30 09:33
MOT test number	694714901324
Result	✓ Passed

MOT #16	2019-07-17 12:30
MOT test number	783116601355
Result	✓ Passed



YX52XPN
report date: 2024-03-29

MOT #15	2019-06-17 11:42
MOT test number	510720144288
Result	🗙 Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Brake pipe excessively corroded front to rear x4 (1.1.11 (c))	
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14	2018-07-03 13:00
MOT test number	807025158752
Result	Passed
Advice Brake pipe corroded, covered in grease or other material front to re	ear and rear (1.1.11 (c))

MOT #13	2017-05-31 10:29
MOT test number	762352717741
Result	✓ Passed
MOT #12	2016-05-23 09:03

MOT test number	868711696567
Result	✓ Passed

MOT #11	2015-05-19 12:40
MOT test number	369009035153
Result	✓ Passed

MOT #10	2014-05-13 10:34
MOT test number	537263434159
Result	✓ Passed





МОТ #9	2013-05-20 11:57
MOT test number	267370743403
Result	✓ Passed
МОТ #8	2012-05-03 14:51
MOT test number	328764722171
Result	✓ Passed
MOT #7	2011-05-09 13:01
MOT test number	165739121140
Result	✓ Passed
МОТ #6	2010-05-20 09:57
MOT test number	844010440157
Result	✓ Passed
MOT #5	2009-06-01 11:49
MOT test number	551522259167
Result	✓ Passed
MOT #4	2008-05-16 12:20
MOT test number	680977738113
Result	✓ Passed
NOT #2	
MOT #3	2007-05-16 10:25
MOT test number	191426537116
Result	✓ Passed
Notice Cut in n/s front tyre wall & damage on n/s & o/s/f tyre wall kerb protecters	
Advice Offside Front brake disc slightly scored (3.5.1h)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #2	2006-11-01 11:56
MOT test number	644185106311
Result	✓ Passed
MOT #1	2005-11-02 12:12
MOT test number	962996205309
Result	✓ Passed





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et a
Date	*
Category	AMP
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-10-30
Last registration	2023-07-28
Complete history	<u>See info</u>



Registration #1	2002-10-30	18 mi
Registration #2	2005-11-02	10.540 mi
Registration #3	2006-11-01	12.788 mi
Registration #4	2007-05-16	16.265 mi
Registration #5	2008-05-16	21.194 mi
Registration #6	2009-06-01	24.217 mi
Registration #7	2010-05-20	28.270 mi
Registration #8	2011-05-09	30.391 mi
Registration #9	2012-05-03	34.459 mi
Registration #10	2013-05-20	39.739 mi
Registration #11	2014-05-13	44.916 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.117 esi
Registration #21		11.117 mi
Registration #22		11.777 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1856 mm
Height	1345 mm
Length	4041 mm
Wheel base	2429 mm
Kerb weight	1395 kg
Max. allowed weight	1850 kg
Additional information	
Fuel tank capacity	62
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles CarCheck.co.uk	2 page 13/13