



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	BIPPER HDI S
Colour	White
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-05
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-12
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	37
Total items failed	4

MOT #14 2023-09-13 13:59

MOT test number 370878871287

Result ✓ Passed

Next expiry date 2024-09-12

Advice Nearside Front Oil leak, but not excessive Driveshaft seal has slight oil seepage (8.4.1 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13 2023-09-07 09:43

MOT test number 312848953434

Result ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Advice** Nearside Front Oil leak, but not excessive Driveshaft seal has slight oil seepage (8.4.1 (a) (i))

MOT #12 2022-09-06 11:30

MOT test number 146311264796

Result ✓ Passed

**MOT #11** 2022-09-06 08:46**MOT test number** 681585433814**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Windscreen wiper not working (3.4 (a))**MOT #10** 2021-08-10 12:25**MOT test number** 654857921061**Result** ✓ Passed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #9** 2020-09-11 12:51**MOT test number** 886245146954**Result** ✓ Passed

**MOT #8** 2019-09-02 11:12**MOT test number** 842845893896**Result** ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2019-09-02 10:39**MOT test number** 538649839605**Result** ✗ Failed

- Fail** Horn not working (7.7 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2018-09-26 11:09**MOT test number** 700527790162**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**Minor** Offside Rear Brake hose slightly twisted (1.1.12 (b) (i))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2017-09-30 08:38**MOT test number** 492878953010**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #4** 2016-09-24 08:06**MOT test number** 915351855095**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a slightly worn shock absorber pivot centre shaft (2.7.4)**Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #3	2015-09-25 16:17
MOT test number	143027820852
Result	✓ Passed
Advice	Offside Front slight wear to inner edge
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Rears and n/s/f tyres slight cracking
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Shock absorber has a slightly worn shock absorber pivot centre shaft (2.7.4)

MOT #2	2014-09-27 09:49
MOT test number	367900374238
Result	✓ Passed
MOT #1	2013-09-24 12:54
MOT test number	877467263206
Result	✓ Passed
Advice	Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)



Tax & MOT check

X

Untaxed

Tax expired:
1 February 2024

✓

MOT

Expires:
12 September 2024

Tax status	Expired at 1 February 2024
Days left	89 days too late
MOT expiry date	12 September 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-30
Last registration	2023-09-13
Complete history	See info



Registration #1	2010-09-30	21 mi
Registration #2	2013-09-24	26.473 mi
Registration #3	2014-09-27	28.045 mi
Registration #4	2015-09-25	29.262 mi
Registration #5	2016-09-24	30.218 mi
Registration #6	2017-09-30	31.132 mi
Registration #7	2018-09-26	32.051 mi
Registration #8	2019-09-02	32.742 mi
Registration #9	2020-09-02	33.377 mi
Registration #10	2021-09-02	34.012 mi
Registration #11	2022-09-02	34.647 mi
Registration #12	2023-09-13	35.282 mi
Registration #13	2024-03-29	35.917 mi
Registration #14	2024-03-29	36.552 mi
Registration #15	2024-03-29	37.187 mi
Registration #16	2024-03-29	37.822 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2019 mm
Height	1721 mm
Length	3864 mm
Kerb weight	1090 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982664026