





report date: 2024-03-29

General information

Make	JAGUAR
Model	XKR XKR COUPE
Colour	Silver
Year of manufacture	2002
Top speed	155 mph
0 - 60 mph	5.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	400 BHP
Max. torque	541 Nm at 3.500 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.7 mpg
Consumption extra urban	31.0 mpg
Consumption combined	22.8 mpg
CO2 emission	304 g/km
CO2 label	М



CarCheck.co.uk page 1/14




Internet history

Entry 5

Date 2023-11-16

Pictures 36

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 4

Date 2023-08-16

Pictures 36

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 3

Date 2022-03-27

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2021-09-11
Pictures	50

CarCheck.co.uk page 2/14

View report









source: cargurus.co.uk


Entry 1


Date 2021-09-10

Pictures 68

Listing price <u>View report</u>









source: autotrader.co.uk



✓ Passed

MOT history

Result

MOT expiry date	2024-02-22
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	25
Total items failed	8

MOT #22	2023-02-23 12:55
MOT test number	493810392904
Result	✓ Passed
Next expiry date	2024-02-22

MOT #21	2023-02-21 17:52
MOT test number	312320935871
Result	× Failed
Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #20	2021-12-16 16:50
MOT test number	678283544256
Result	✓ Passed
MOT #19	2020-09-24 15:41
MOT test number	256078769525
Result	✓ Passed
MOT #18	2019-10-17 09:38
MOT test number	860459136400

CarCheck.co.uk page 3/14



MOT #17 2018-04-21 09:35

MOT test number 101756626239

Result ✓ Passed

MOT #16 2017-04-18 10:58

MOT test number 683714967201

Result

Passed

MOT #15 2016-04-18 12:44

MOT test number 728766831608

Result
✓ Passed

MOT #14 2016-04-16 08:16

MOT test number 661575697170

Result X Failed

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #13 2015-04-28 09:57

MOT test number 598688715182

Result
✓ Passed

Advice Nearside Outer Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12 2014-04-28 09:21

MOT test number 468288914136

Result \(\sqrt{Passed} \)

Advice Nearside Outer Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Notice Near side front floor panel rust hole. Off side front floor panel showing signs of rusting.

CarCheck.co.uk page 4/14



BK52YRY

report date: 2024-03-29

X Failed

MOT #11 2013-04-17 11:34

MOT test number 856207603139

Result ✓ Passed

Advice Nearside Outer Front Lower Tie bar/rod ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #10 2012-04-13 09:31

MOT test number 918004802161

Result \(\sqrt{Passed} \)

Advice Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)

Notice Both front tyres cracking on outer edge

MOT #9 2011-04-27 10:26

MOT test number 248367511180

Result \rightarrow Passed

Notice Both front tyres showing signs of perrishing

MOT #8 2011-04-26 12:25

MOT test number 265796311172

2007,300,1117

Notice Both front tyres showing signs of perrishing

Result

Fail Offside Inner Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #7 2010-04-20 11:52

MOT test number 203560010430

CarCheck.co.uk page 5/14



MOT #6 2010-04-19 12:32

MOT test number 842009700163

Result X Failed

Fail Parking brake lever has no reserve travel (3.1.6b)

Fail Rear brake disc excessively pitted (3.5.1h)

Fail Front brake disc excessively pitted (3.5.1h)

Fail Front front brake juddering severely (3.7.A.2b)

MOT #5 2009-04-21 10:28

MOT test number 391621219130

Result \square Passed

Notice Suspension joint nearside lower dust cover split/missing

MOT #4 2008-04-21 17:42

MOT test number 251032918160

Advice Offside Inner Front brake disc slightly pitted (3.5.1h)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Inner Front brake disc slightly pitted (3.5.1h)

Notice Both front flexible brake hoses catching slightly on front antiroll bar

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/14



✓ Passed

MOT #3 2008-04-21 09:22

MOT test number 442622218133

Result X Failed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Inner Front brake disc slightly pitted (3.5.1h)

Notice Both front flexible brake hoses catching slightly on front antiroll bar

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Inner Front brake disc slightly pitted (3.5.1h)

MOT #2 2007-04-20 12:20

MOT test number 634480417115

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Offside rear tyre has nail in tread

Result

MOT #1 2006-04-26 11:30

MOT test number 432647616195

Result

Passed

CarCheck.co.uk page 7/14





Tax & MOT check

Tax expired: 28 January 2020



X **MOT**

Expired: 22 February 2024

Tax status	Expired at 28 January 2020
Days left	1554 days too late
MOT expiry date	22 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
PROPERTY.	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2002-09-27
Last registration	2023-02-23
Complete history	See info



Registration #1	2002-09-27	21 mi
Registration #2	2006-04-26	30.457 mi
Registration #3	2007-04-20	41.538 mi
Registration #4	2008-04-21	48.280 mi
Registration #5	2008-04-21	48.281 mi
Registration #6	2009-04-21	55.176 mi
Registration #7	2010-04-19	62.236 mi
Registration #8	2010-04-20	62.238 mi
Registration #9	2011-04-26	68.232 mi
Registration #10	2011-04-27	68.255 mi
Registration #11	2012-04-13	70.096 mi
Registration #12	2013-04-17	70.457 mi
Registration #13	2014-04-28	70.592 mi
Registration #14	2015-04-28	71.672 mi
Registration #15		11.177 mi
Registration #16		11.117 es
Registration #17		11.177 mi
Registration #18		11.117 es
Registration #19		11.777 mi
Registration #20		11.117 es
Registration #21		11.777 es
Registration #22		11.117 es
Registration #23		11.227 mi
Registration #24		11.177 es
Registration #25		11.777 es
Registration #26		0.00 44
CarCheck.co.uk		page 13/14

Registration #27

Registration #28

More info >

mn.n.n



Dimensions & weight

Width	2015 mm
Height	1296 mm
Length	4760 mm
Wheel base	2588 mm
Kerb weight	1735 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	3B0209051912

CarCheck.co.uk page 14/14