





report date: 2024-03-28

General information

Make	FIAT
Model	TALENTO 16V MULTIJET II
Colour	White
Year of manufacture	2016
Top speed	103 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	43.5 mpg
CO2 emission	170 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



LD66YBL

report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-10

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT	history
1.101	iliocol y

MOT expiry date	2024-09-29
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	17
Total items failed	4

MOT #8	2023-09-21 07:47
MOT test number	856863918510
Result	✓ Passed
Next expiry date	2024-09-29

MOT #7	2022-09-29 09:10
MOT test number	259596049153
Result	✓ Passed
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple la	amps or light sources (4.7.1

MOT #6	2021-09-02 13:31
MOT test number	353886570911
Result	✓ Passed

MOT #5	2021-09-02 10:46
MOT test number	772284805287
Result	X Failed
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

CarCheck.co.uk page 3/12



LD66YBL

report date: 2024-03-28

MOT test number

403902538727

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Nail in tyre

MOT #3 2020-09-29 16:51 **MOT** test number 939309135284 Result × Failed Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a)) Advice Offside Rear Nail in tyre Advice Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) **Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2		2019-09-12 15:30
MOT test	number	590043488577
Result		✓ Passed
Advice and rim sl	Nearside Front Tyre has a cut but not deep enough to reach the ply or ghtly distorted (5.2.3 (d) (i))	cords cut on outer side wall
Advice	Offside Rear lamp unit cracked	
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or	cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/12



MOT #1 2019-09-12 12:43

MOT test number 128987857366

Result

× Failed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords cut on outer side wall and rim slightly distorted (5.2.3 (d) (i))

Advice Offside Rear lamp unit cracked

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords marked (5.2.3 (d) (i))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



LD66YBL

report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when mistery	
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
STATE OF THE PARTY	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SIN
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-11-15
Last registration	2023-09-21
Complete history	See info



Registration #1	2016-11-15	14 mi
Registration #2	2019-09-12	74.854 mi
Registration #3	2019-09-12	74.854 mi
Registration #4	2020-09-29	93.753 mi
Registration #5	2020-09-30	93.753 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #7 Registration #8		11.77 m
		11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4999 mm
Kerb weight	1726 kg
Max. allowed weight	2800 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	C003366

CarCheck.co.uk page 12/12