



report date: 2024-03-28

General information

| | |
|---------------------|------------------|
| Make | CITROEN |
| Model | BERLINGO HDI XTR |
| Colour | Grey |
| Year of manufacture | 2011 |
| Top speed | 107 mph |
| 0 - 60 mph | 14.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 109 BHP |
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.1 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-29 |
| Pictures | 9 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-19 |
| MOT pass rate | 91 % |
| MOT passed | 10 |
| Failed MOT tests | 1 |
| Total advice items | 15 |
| Total items failed | 0 |

| | |
|------------------|------------------|
| MOT #11 | 2023-07-04 10:13 |
| MOT test number | 617657397979 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-19 |

| | |
|-----------------|------------------|
| MOT #10 | 2022-07-20 13:31 |
| MOT test number | 126424793123 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #9 | 2021-04-30 09:39 |
| MOT test number | 675673478597 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #8 | 2019-11-19 10:24 |
| MOT test number | 889398196957 |
| Result | ✓ Passed |

**MOT #7**

2018-11-09 15:41

MOT test number

176053663656

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 3mm (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing 3mm (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing 3mm (5.2.3 (d) (ii))

MOT #6

2018-11-09 10:05

MOT test number

244673486338

Result

✗ Failed

- Advice** Offside Rear Brake pad(s) wearing thin brake pad broken up (1.1.13 (a) (ii))
- MAJOR** Brake performance not tested offside rear brake pad broken up (1.2.1 (g))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing 3mm (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing 3mm (5.2.3 (d) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 3mm (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5

2017-11-21 09:40

MOT test number

664828292205

Result

✓ Passed

- Advice** Unable to fully check rear seat belts as rear seats removed

**MOT #4** 2016-11-30 15:29**MOT test number** 464946888113**Result** ✓ Passed**Advice** Rear Passenger seat(s) missing at time of test**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2016-01-07 11:53**MOT test number** 566781225125**Result** ✓ Passed**MOT #2** 2015-03-26 11:30**MOT test number** 905635685021**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2014-06-05 11:55**MOT test number** 227856454137**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 95 |
| MOT expiry date | 19 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 0 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2011-08-12 |
| Last registration | 2023-07-04 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-08-12 | 8 mi |
| Registration #2 | 2014-06-05 | 7.815 mi |
| Registration #3 | 2015-03-26 | 11.100 mi |
| Registration #4 | 2016-01-07 | 14.668 mi |
| Registration #5 | 2016-11-30 | 18.024 mi |
| Registration #6 | 2017-11-21 | 19.897 mi |
| Registration #7 | 2018-11-09 | 21.281 mi |
| Registration #8 | 2019-05-29 | 22.277 mi |
| Registration #9 | 2019-05-29 | 22.277 mi |
| Registration #10 | 2019-05-29 | 22.277 mi |
| Registration #11 | 2019-05-29 | 22.277 mi |
| Registration #12 | 2019-05-29 | 22.277 mi |
| Registration #13 | 2019-05-29 | 22.277 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1803 mm |
| Length | 4380 mm |
| Wheel base | 2728 mm |
| Kerb weight | 1426 kg |
| Max. allowed weight | 2065 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | JBEV3007920 |