



KP08YNK

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS FSI
Colour	Silver
Year of manufacture	2008
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	200 Nm at 3.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	41.5 mpg
Consumption combined	33.2 mpg
CO2 emission	198 g/km
CO2 label	J







Internet history

Entry 1

Date	2021-07-20
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-24
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	49
Total items failed	14

MOT #22 2023-07-25 14:03

MOT test number 233542235968

Result ✓ Passed

Next expiry date 2024-07-24

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice Top engine mount slightly worn

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #21 2022-08-30 12:34

MOT test number 435796608338

Result ✓ Passed

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #20**

2022-08-29 10:31

MOT test number

597869665072

Result**✗ Failed**

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened STRONG ADVICE (1.1.14 (a) (ii))

Fail Nearside Rear Valve stem seriously damaged (5.2.3 (j))

Fail Offside Front Side repeater not working (4.4.1 (a) (ii))

Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19

2021-09-07 14:09

MOT test number

611094213124

Result**✓ Passed****MOT #18**

2021-09-02 09:15

MOT test number

304635752959

Result**✗ Failed**

Advice Offside Rear Tyre worn close to legal limit/worn on edge tyre worn on inner edge (5.2.3 (e))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #17**

2020-08-24 10:04

MOT test number

905042709790

Result

✓ Passed

Advice Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement outer bush deteriorating (5.3.4 (a) (i))

Advice Nearside Front tyre 2.5mm approx.

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Front Valve stem slightly damaged cracking (5.2.3 (j))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Outer tyre cut to outer wall / 3mm tread

Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement outer bush deteriorating (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracking in tread / worn inner edge (5.2.3 (d) (ii))

Advice Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Valve stem slightly damaged cracking (5.2.3 (j))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

MOT #16

2019-08-27 07:09

MOT test number

697302180376

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

MOT #15

2018-08-23 07:54

MOT test number

695074854008

Result

✓ Passed

**MOT #14** 2018-08-22 11:01**MOT test number** 162413894507**Result** ✗ Failed**Advice** Nearside Front tyre wearing on inner edge 3mm**Fail** Offside Front Tyre has ply or cords exposed cords exposed inner edge (5.2.3 (d) (ii))**MOT #13** 2017-08-21 15:39**MOT test number** 959774194647**Result** ✓ Passed**MOT #12** 2017-08-21 09:49**MOT test number** 591031989744**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #11** 2016-08-20 08:22**MOT test number** 854156191510**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2015-08-12 15:16**MOT test number** 744695798366**Result** ✓ Passed**Advice** Plastic under trays fitted obscuring some testable items**Advice** Both front tyres wearing badly on edges, alignment issue?

**MOT #9** 2015-08-12 07:45**MOT test number** 845818319023**Result** ✗ Failed**Advice** Plastic under trays fitted obscuring some testable items**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Both front tyres wearing badly on edges, alignment issue?**MOT #8** 2014-08-05 09:34**MOT test number** 637527314237**Result** ✓ Passed**MOT #7** 2014-08-05 09:34**MOT test number** 935607114220**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high and too far to the right. (1.8)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #6** 2013-08-02 17:34**MOT test number** 235194113287**Result** ✓ Passed

**MOT #5** 2013-08-01 16:06**MOT test number** 596943513230**Result** ✗ Failed**Notice** WHEEL/TYRE ALIGNMENT ISSUED > CHECK REQUIRED**Pass with rectification** Headlamp aim too low (1.8)**Advice** Tyre worn close to the legal limit (4.1.E.1)**Notice** DISCS ARE WORN > CHECK MINIMUM ADVISED THICKNESS**Fail** Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-08-02 10:09**MOT test number** 886615612210**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-08-02 10:09**MOT test number** 759535812223**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (1.8)



MOT #2	2011-08-03 15:14
MOT test number	599055511259
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-07-28 14:35
MOT test number	315439301405
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Outer Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

X

Untaxed

Tax expired:
6 August 2023

✓

MOT

Expires:
24 July 2024

Tax status	Expired at 6 August 2023
Days left	266 days too late
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-05-12
Last registration	2023-07-25
Complete history	See info



Registration #1	2008-05-12	12 mi
Registration #2	2011-07-28	24.576 mi
Registration #3	2011-08-03	24.740 mi
Registration #4	2012-08-02	37.313 mi
Registration #5	2013-08-01	50.128 mi
Registration #6	2013-08-02	50.128 mi
Registration #7	2014-08-05	61.023 mi
Registration #8	2015-08-12	70.880 mi
Registration #9	2015-08-12	70.880 mi
Registration #10	2016-08-20	74.281 mi
Registration #11	2017-08-21	80.592 mi
Registration #12	2018-08-21	85.000 mi
Registration #13	2019-08-21	85.000 mi
Registration #14	2020-08-21	85.000 mi
Registration #15	2021-08-21	85.000 mi
Registration #16	2022-08-21	85.000 mi
Registration #17	2023-08-21	85.000 mi
Registration #18	2024-08-21	85.000 mi
Registration #19	2025-08-21	85.000 mi
Registration #20	2026-08-21	85.000 mi
Registration #21	2027-08-21	85.000 mi
Registration #22	2028-08-21	85.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1590 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BVY 139152