



AJ59ZGZ

report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	White
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-06-13
Pictures	1
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #16	2023-07-03 10:23
MOT test number	300040239177
Result	✓ Passed
Next expiry date	2024-07-02
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front head lamp image deteriorating

MOT #15	2022-06-22 13:38
MOT test number	975640201581
Result	✓ Passed
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #14	2022-06-17 13:43
MOT test number	559886668450
Result	✗ Failed
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13	2021-09-15 13:02
MOT test number	241263881926
Result	✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2021-09-15 13:02

MOT test number

283449826866

Result**✗ Failed****Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Rear Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11**

2020-09-15 07:12

MOT test number

292126917038

Result**✓ Passed****MOT #10**

2020-09-14 13:50

MOT test number

427109106240

Result**✗ Failed****Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Anti-roll bar linkage missing (5.3.3 (a) (ii))**MOT #9**

2019-05-15 13:40

MOT test number

878327337990

Result**✓ Passed****MOT #8**

2018-01-31 10:38

MOT test number

684779905658

Result**✓ Passed****Advice** Offside Front tyre worn on inner edge

**MOT #7** 2018-01-31 10:38**MOT test number** 108982985262**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front tyre worn on inner edge**MOT #6** 2016-12-22 14:14**MOT test number** 108211510791**Result** ✓ Passed**MOT #5** 2016-04-21 12:57**MOT test number** 213897160410**Result** ✓ Passed**MOT #4** 2015-04-01 16:59**MOT test number** 399801495091**Result** ✓ Passed**Notice** N/s/f tyre wall starting to crack**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/f tyre worn on inner edge**MOT #3** 2015-04-01 09:47**MOT test number** 839391995082**Result** ✗ Failed**Notice** N/s/f tyre wall starting to crack**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/f tyre worn on inner edge**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)



MOT #2	2013-11-02 12:13
MOT test number	409616303497
Result	✓ Passed

MOT #1	2012-11-05 10:02
MOT test number	487130712339
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-13
Last registration	2023-07-03
Complete history	See info



Registration #1	2009-11-13	24 mi
Registration #2	2012-11-05	28.332 mi
Registration #3	2013-11-02	38.003 mi
Registration #4	2015-04-01	47.075 mi
Registration #5	2015-04-01	47.075 mi
Registration #6	2016-04-21	52.010 mi
Registration #7	2016-12-22	58.707 mi
Registration #8	2018-01-31	69.011 mi
Registration #9	2018-01-31	69.011 mi
Registration #10	2019-05-29	75.377 mi
Registration #11	2019-05-29	75.377 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	704037