



report date: 2024-03-29

General information

Make	MINI
Model	COOPER COOPER D
Colour	Blue
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



## MOT history

MOT expiry date	2025-03-05
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	18
Total items failed	5

MOT #14	2024-03-06 09:56
MOT test number	165182415430
Result	✓ Passed
Next expiry date	2025-03-05
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2023-02-28 12:23
MOT test number	409435617241
Result	✓ Passed
Advice	Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #12	2022-03-03 14:22
MOT test number	240409203392
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #11**

2022-03-03 12:56

**MOT test number**

187054912465

**Result**

✗ Failed

- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #10**

2021-01-27 09:14

**MOT test number**

543055888659

**Result**

✓ Passed

**MOT #9**

2020-10-07 14:13

**MOT test number**

466009513682

**Result**

✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8**

2019-10-11 08:38

**MOT test number**

734071782184

**Result**

✓ Passed

- Minor** Nearside Front Windscreen wiper blade defective wiper blade insecure (3.4 (b) (i))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #7** 2018-10-03 11:15**MOT test number** 382760930107**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-10-03 11:14**MOT test number** 477135934395**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2017-10-12 12:10**MOT test number** 912686330237**Result** ✓ Passed**MOT #4** 2016-10-07 15:04**MOT test number** 735739459381**Result** ✓ Passed**MOT #3** 2016-10-07 15:04**MOT test number** 853328677281**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)



MOT #2	2015-09-29 15:35
MOT test number	814750571312
Result	✓ Passed
MOT #1	2014-10-17 09:18
MOT test number	535500294290
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
5 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	5 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-07-02
Last registration	2024-03-06
Complete history	<a href="#">See info</a>



Registration #1	2012-07-02	20 mi
Registration #2	2014-10-17	9.467 mi
Registration #3	2015-09-29	30.817 mi
Registration #4	2016-10-07	44.375 mi
Registration #5	2016-10-07	44.375 mi
Registration #6	2017-10-12	50.359 mi
Registration #7	2018-10-03	56.958 mi
Registration #8	2018-10-03	56.958 mi
Registration #9	2019-10-03	63.557 mi
Registration #10	2019-10-03	63.557 mi
Registration #11	2019-10-03	63.557 mi
Registration #12	2019-10-03	63.557 mi
Registration #13	2019-10-03	63.557 mi
Registration #14	2019-10-03	63.557 mi
Registration #15	2019-10-03	63.557 mi
Registration #16	2019-10-03	63.557 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	70817962