



report date: 2024-03-28

General information

Make	VAUXHALL
Model	TIGRA SXI 16V TWINPORT
Colour	Blue
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg





Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: autoonline.co.uk

**MOT history**

MOT #17	2021-04-15 07:45
MOT test number	214094864208
Result	✓ Passed
Next expiry date	2022-04-14

MOT #16	2020-03-24 12:05
MOT test number	844778741048
Result	✓ Passed

MOT #15	2020-03-23 16:42
MOT test number	412871267981
Result	✗ Failed

Advice Central Front Upper Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #14	2019-04-05 08:29
MOT test number	654725208065
Result	✓ Passed

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #13	2018-04-06 14:16
MOT test number	348241273204
Result	✓ Passed



MOT #12	2017-05-11 13:38
----------------	------------------

MOT test number	869357757878
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #11	2016-09-08 13:02
----------------	------------------

MOT test number	117057169447
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2016-07-01 11:52
----------------	------------------

MOT test number	247354533538
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2015-08-05 13:12
---------------	------------------

MOT test number	528697915239
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2015-08-05 11:35
---------------	------------------

MOT test number	366437715417
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification Offside Headlamp aim too low (1.8)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Pass with rectification Nearside Headlamp aim too low (1.8)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**MOT #7** 2014-07-30 15:11**MOT test number** 517521614242**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Both the Rear tyres are perishing..**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2014-07-29 15:46**MOT test number** 605030914226**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Both the Rear tyres are perishing..**MOT #5** 2013-07-23 10:01**MOT test number** 729194703237**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-07-25 16:03**MOT test number** 579327602210**Result** ✓ Passed**Notice** Scratch on windscreen caused by defective wiper blade**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front number plate damaged

**MOT #3**

2012-07-25 14:57

MOT test number

487977802231

Result**✗ Failed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front number plate damaged**Fail** Offside Front Headlamp aim too high (1.8)**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Nail in offside rear tyre**Notice** Scratch on windscreen caused by defective wiper blade**Fail** Nearside Front Headlamp aim too high (1.8)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2**

2011-06-07 11:44

MOT test number

139298251169

Result**✓ Passed****Notice** Nail in offside rear tyre**Notice** Offside rear tyre slightly distorted**MOT #1**

2010-03-03 12:53

MOT test number

362512460094

Result**✓ Passed****Notice** OFF SIDE FRONT TYRE SIDE WALL DAMAGED.**Notice** NEAR SIDE WIPER REQUIRES RENEWAL A.S.A.P.



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	GU07DXD
Plate since	2019-06-29
Current registration	GU07DXD
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-01
Last registration	2021-04-15
Complete history	See info



Registration #1	2007-03-01	24 mi
Registration #2	2010-03-03	23.461 mi
Registration #3	2011-06-07	35.815 mi
Registration #4	2012-07-25	40.876 mi
Registration #5	2012-07-25	40.876 mi
Registration #6	2013-07-23	43.503 mi
Registration #7	2014-07-29	47.049 mi
Registration #8	2014-07-30	47.049 mi
Registration #9	2015-08-05	49.989 mi
Registration #10	2015-08-05	49.989 mi
Registration #11	2016-08-05	52.929 mi
Registration #12	2017-08-05	55.869 mi
Registration #13	2018-08-05	58.809 mi
Registration #14	2019-08-05	61.749 mi
Registration #15	2020-08-05	64.689 mi
Registration #16	2021-04-15	67.629 mi
Registration #17	2022-04-15	70.569 mi
Registration #18	2023-04-15	73.509 mi
Registration #19	2024-03-28	76.449 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1753 mm
Height	1413 mm
Length	4288 mm
Wheel base	2614 mm
Kerb weight	1180 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	19KX6550