



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D4 SE NAV
Colour	Blue
Year of manufacture	2014
Top speed	140 mph
0 - 60 mph	7.9 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT expiry date	2024-08-18
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #9 2023-07-26 11:16**MOT test number** 379767141753**Result** Passed**Next expiry date** 2024-08-18**Advice** Nearside Rear Tyre slightly damaged misshaped inner edge (5.2.3 (d) (ii))**Advice** Exhaust has a minor leak of exhaust gases middle pipe (6.1.2 (a))**Advice** Exhaust middle pipe cracked**Advice** Offside Rear Tyre slightly damaged misshaped inner edge (5.2.3 (d) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #8** 2022-08-01 12:36**MOT test number** 967586140323**Result** Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2021-08-11 13:00**MOT test number** 188194569443**Result** Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #6** 2020-08-19 10:56**MOT test number** 979579858328**Result** ✓ Passed**MOT #5** 2019-08-19 11:36**MOT test number** 783859555924**Result** ✓ Passed**Advice** Undertrays fitted**MOT #4** 2018-11-10 15:22**MOT test number** 395646252710**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2018-11-09 12:25**MOT test number** 684205904369**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #2** 2017-11-10 16:44**MOT test number** 361928084960**Result** ✓ Passed**MOT #1** 2016-11-25 04:22**MOT test number** 530030096398**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
18 August 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	18 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-12
Last registration	2023-07-26
Complete history	See info



Registration #1	2014-03-12	21 mi
Registration #2	2016-11-25	82.169 mi
Registration #3	2017-11-10	87.602 mi
Registration #4	2018-11-09	95.286 mi
Registration #5	2018-11-10	95.286 mi
Registration #6	2019-08-19	97.919 mi
Registration #7	2019-08-20	98.277 mi
Registration #8	2019-08-20	98.277 mi
Registration #9	2019-08-20	98.277 mi
Registration #10	2019-08-20	98.277 mi
Registration #11	2019-08-20	98.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4854 mm
Wheel base	2835 mm
Kerb weight	1675 kg
Max. allowed weight	2230 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1148132