



General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE PLUS TDI
Colour	Black
Year of manufacture	2010
Top speed	119 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.986 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-09-25
Pictures	41
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2023-12-13
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	33
Total items failed	3

MOT #15	2022-12-14 14:13
MOT test number	433969458872
Result	✓ Passed
Next expiry date	2023-12-13

MOT #14	2021-11-10 10:22
MOT test number	383522853520
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing Wall Slightly damaged (5.2.3 (d) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened N/S AND O/S (1.1.14 (a) (ii))

MOT #13	2021-11-08 18:57
MOT test number	273185035484
Result	✗ Failed
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Offside Front Side repeater not working (4.4.1 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing Wall Slightly damaged (5.2.3 (d) (ii))
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened N/S AND O/S (1.1.14 (a) (ii))

**MOT #12** 2020-11-30 13:17**MOT test number** 444422015125**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2020-11-30 11:55**MOT test number** 988782205605**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #10** 2019-11-01 09:23**MOT test number** 393237806599**Result** ✓ Passed**MOT #9** 2018-10-26 11:49**MOT test number** 263244886322**Result** ✓ Passed**Advice** Offside Rear Nail in tyre 235/45r17**Advice** Offside Front Tyre worn close to legal limit/worn on edge 235/45r17 (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 235/45r17 (5.2.3 (e))

**MOT #8** 2018-10-26 08:58**MOT test number** 127644504357**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 235/45r17 (5.2.3 (e))**MAJOR** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Rear Nail in tyre 235/45r17**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 235/45r17 (5.2.3 (e))**MOT #7** 2017-11-01 16:02**MOT test number** 257720879085**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** No emissions detected at time of test.**MOT #6** 2017-11-01 14:27**MOT test number** 821482114487**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** No emissions detected at time of test.**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2016-11-10 15:00**MOT test number** 463394787432**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2016-11-10 10:29**MOT test number** 427813057203**Result** ✗ Failed**Fail** Offside Side repeater not working (1.4.A.2c)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Side repeater not working (1.4.A.2c)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-11-26 15:22**MOT test number** 996757425916**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-10-28 16:41**MOT test number** 136951504398**Result** ✓ Passed**MOT #1** 2013-06-10 11:15**MOT test number** 887801063160**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 June 2023

✕  
MOT

Expired:  
13 December 2023

Tax status	Expired at 1 June 2023
Days left	333 days too late
MOT expiry date	13 December 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BT10XBA</b>
Plate since	2019-06-29
Current registration	 <b>BT10XBA</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-16
Last registration	2022-12-14
Complete history	<a href="#">See info</a>



Registration #1	2010-07-16	26 mi
Registration #2	2013-06-10	23.514 mi
Registration #3	2014-10-28	34.531 mi
Registration #4	2015-11-26	51.753 mi
Registration #5	2016-11-10	64.414 mi
Registration #6	2016-11-10	64.414 mi
Registration #7	2017-11-01	67.719 mi
Registration #8	2017-11-01	67.719 mi
Registration #9	2018-10-26	92.662 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1435 kg
Max. allowed weight	2080 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CBD 458230