



General information

Make	FIAT
Model	SEICENTO ACTIVE SPORT
Colour	Black
Year of manufacture	2003
Top speed	93 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	54 BHP
Max. torque	87 Nm at 2.750 rpm
Engine capacity	1.108 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg
CO2 emission	143 g/km
CO2 label	F







Internet history

Entry 1

Date	2022-02-04
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-04
MOT pass rate	83 %
MOT passed	19
Failed MOT tests	4
Total advice items	21
Total items failed	2

MOT #23 2024-01-23 15:24

MOT test number 675400865012

Result ✓ Passed

Next expiry date 2025-02-04

Advice Brake pipe corroded, covered in grease or other material Offside and nearside front (1.1.11 (c))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #22 2024-01-22 09:54

MOT test number 707086867522

Result ✗ Failed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**Advice** Brake pipe corroded, covered in grease or other material Offside and nearside front (1.1.11 (c))

MOT #21 2023-01-25 14:37

MOT test number 993467612117

Result ✓ Passed**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #20** 2023-01-25 11:23**MOT test number** 349623982433**Result** ✗ Failed**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MAJOR** Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #19** 2022-02-05 09:23**MOT test number** 568731950808**Result** ✓ Passed**MOT #18** 2022-02-02 13:33**MOT test number** 928569574317**Result** ✗ Failed**Advice** All over general under body corrosion**MAJOR** Offside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Brake pipe excessively corroded (1.1.11 (c))**MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #17** 2021-06-16 15:40**MOT test number** 575168978398**Result** ✓ Passed

**MOT #16** 2021-06-16 15:40**MOT test number** 278779637020**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Windscreen washer not working (3.5 (a))**MOT #15** 2020-06-09 10:14**MOT test number** 575798517813**Result** ✓ Passed**MOT #14** 2019-06-28 08:47**MOT test number** 744441199074**Result** ✓ Passed**MOT #13** 2018-06-13 13:54**MOT test number** 323686696580**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2017-06-15 14:34**MOT test number** 557118974531**Result** ✓ Passed**MOT #11** 2016-06-24 14:13**MOT test number** 591140801320**Result** ✓ Passed**MOT #10** 2015-06-16 13:32**MOT test number** 847747565179**Result** ✓ Passed



MOT #9	2014-06-26 09:33
MOT test number	638887674155
Result	✓ Passed
MOT #8	2013-06-20 14:08
MOT test number	215291473129
Result	✓ Passed
MOT #7	2012-06-28 15:54
MOT test number	245470282437
Result	✓ Passed
MOT #6	2011-06-23 12:24
MOT test number	417414671188
Result	✓ Passed
MOT #5	2010-06-28 14:08
MOT test number	254299970405
Result	✓ Passed
MOT #4	2009-06-10 11:05
MOT test number	500331869148
Result	✓ Passed
MOT #3	2008-06-27 11:00
MOT test number	761919078138
Result	✓ Passed



MOT #2	2007-06-29 13:25
MOT test number	123780787151
Result	✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #1	2006-06-30 11:11
MOT test number	762821686101
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
4 February 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-06-30
Last registration	2024-01-23
Complete history	See info



Registration #1	2003-06-30	15 mi
Registration #2	2006-06-30	6.039 mi
Registration #3	2007-06-29	8.247 mi
Registration #4	2008-06-27	10.083 mi
Registration #5	2009-06-10	11.292 mi
Registration #6	2010-06-28	12.407 mi
Registration #7	2011-06-23	13.386 mi
Registration #8	2012-06-28	14.445 mi
Registration #9	2013-06-20	15.218 mi
Registration #10	2014-06-26	16.042 mi
Registration #11	2015-06-16	17.030 mi
Registration #12	2016-06-24	17.958 mi
Registration #13	2017-06-15	19.209 mi
Registration #14	2018-06-20	20.377 mi
Registration #15	2019-06-20	21.577 mi
Registration #16	2020-06-20	22.777 mi
Registration #17	2021-06-20	23.977 mi
Registration #18	2022-06-20	25.177 mi
Registration #19	2023-06-20	26.377 mi
Registration #20	2024-01-23	27.577 mi
Registration #21	2024-01-23	28.777 mi
Registration #22	2024-01-23	29.977 mi
Registration #23	2024-01-23	31.177 mi
Registration #24	2024-01-23	32.377 mi
Registration #25	2024-01-23	33.577 mi



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1508 mm
Height	1420 mm
Length	3337 mm
Wheel base	2200 mm
Kerb weight	810 kg

Additional information

Fuel tank capacity	38 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1772951