



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC TDCI
Colour	Blue
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-09-04
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2022-09-13
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	37
Total items failed	1

MOT #13	2021-09-14 17:00
MOT test number	983230222232
Result	✓ Passed
Next expiry date	2022-09-13

MOT #12	2020-09-23 10:46
MOT test number	403242070871
Result	✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive engine oil (8.4.1 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))



## MOT #11

2020-09-23 09:50

## MOT test number

697786595132

## Result

✗ Failed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive engine oil (8.4.1 (a) (i))

## MOT #10

2019-10-02 14:06

## MOT test number

159218030795

## Result

✓ Passed

## MOT #9

2019-10-02 09:38

## MOT test number

664437263793

## Result

✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing very perished/cracked (5.2.3 (d) (ii))
- DANGEROUS** Offside Rear Tyre has ply or cords exposed cut to cords, nail in tread and worn to 2mm (5.2.3 (d) (ii))

**MOT #8** 2018-10-03 08:22**MOT test number** 296988512983**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2017-10-17 08:57**MOT test number** 955994499393**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #6** 2017-06-29 09:11**MOT test number** 981391409969**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit wearing inner edge (4.1.E.1)**MOT #5** 2016-06-27 08:35**MOT test number** 537378494680**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear tyre puncture**Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear tyres unevenly worn inner edges**Advice** Front brake fluctuating, but not excessively (3.7.B.3)

**MOT #4** 2015-07-08 16:13**MOT test number** 795669285168**Result** ✓ Passed**Advice** Nearside Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2015-07-07 11:01**MOT test number** 505198785165**Result** ✗ Failed**Fail** Offside Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2014-07-01 15:20**MOT test number** 588912984158**Result** ✓ Passed**Notice** Trailing arm bushes starting to seperate**MOT #1** 2013-07-03 11:59**MOT test number** 727614583184**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
11 April 2022

✕  
MOT

Expired:  
13 September 2022

Tax status	Expired at 11 April 2022
Days left	750 days too late
MOT expiry date	13 September 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	FR10LKX
Plate since	2019-03-29
Current registration	FR10LKX
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-08-13
Last registration	2021-09-14
Complete history	<a href="#">See info</a>



Registration #1	2010-08-13	17 mi
Registration #2	2013-07-03	27.266 mi
Registration #3	2014-07-01	39.589 mi
Registration #4	2015-07-07	54.191 mi
Registration #5	2015-07-08	54.191 mi
Registration #6	2016-06-27	68.960 mi
Registration #7	2017-06-29	85.214 mi
Registration #8	2017-10-17	8.895 mi
Registration #9	2019-05-20	25.277 mi
Registration #10	2019-05-20	25.277 mi
Registration #11	2019-05-20	25.277 mi
Registration #12	2019-05-20	25.277 mi
Registration #13	2019-05-20	25.277 mi
Registration #14	2019-05-20	25.277 mi
Registration #15	2019-05-20	25.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1505 kg
Max. allowed weight	2150 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	AM40965
---------------	---------