



WEZ4658

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH (60BHP)
Colour	Black
Year of manufacture	2009
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-06-26
Pictures	6
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-05-23
Pictures	3
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-04
MOT pass rate	50 %
MOT passed	4
Failed MOT tests	4
Total advice items	11
Total items failed	15

MOT #8	2024-01-05 15:36
MOT test number	322153542874
Result	✓ Passed
Next expiry date	2025-01-04

MOT #7	2023-12-19 15:38
MOT test number	916846881250
Result	✗ Failed
Fail	Nearside Headlamp levelling device inoperative (4.1.5 (a))

MOT #6	2023-01-04 12:06
MOT test number	553352874543
Result	✓ Passed

MOT #5	2022-12-22 08:45
MOT test number	727437832683
Result	✗ Failed
Advice	Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #4** 2022-04-12 14:37**MOT test number** 741118228028**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm tread left (5.2.3 (e))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #3 2022-04-12 11:54**MOT test number** 286569866398**Result** ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Front Anti-roll bar linkage ball joint excessively worn both front (5.3.4 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm tread left (5.2.3 (e))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #2 2021-04-08 15:21**MOT test number** 817734253156**Result** ✓ Passed



MOT #1

2021-04-08 08:18

MOT test number

915092925338

Result

✗ Failed

- Advice

Exhaust has a minor leak of exhaust gases Front flexi-joint. (6.1.2 (a))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail

Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Fail

Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))
- Fail

Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail

Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
- Fail

Rear Registration plate lamp inoperative in the case of a single lamp or all lamps Both. (4.7.1 (b) (ii))
- Fail

Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Fail

Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail

Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail

Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail

Front Windscreen wiper does not clear the windscreen effectively Both Nsf & Osf. (3.4 (b) (ii))
- Fail

Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
4 January 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	4 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-02-13
Last registration	2024-01-05
Complete history	See info



Registration #1	2009-02-13	13 mi
Registration #2	2021-04-08	87.538 mi
Registration #3	2021-04-08	87.539 mi
Registration #4	2021-04-08	87.539 mi
Registration #5	2021-04-08	87.539 mi
Registration #6	2022-04-12	95.627 mi
Registration #7	2022-04-12	95.627 mi
Registration #8	2022-04-12	95.627 mi
Registration #9	2022-04-12	95.627 mi
Registration #10	2022-04-12	95.627 mi
Registration #11	2022-04-12	95.627 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1092 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BBM216615