





report date: 2024-03-29

General information

Make	MINI
Model	JOHN COOPER WORKS AUTO JOHN COOPER WORKS
Colour	Black
Year of manufacture	2013
Top speed	147 mph
0 - 60 mph	6.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	208 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	39.8 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/11



RK13OCU report date: 2024-03-29

Internet history

Entry 3

Date 2022-11-26

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-12-27
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2021-10-15
Pictures	37

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-05-26
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	4
Total items failed	1

MOT #10	2023-05-02 10:06
MOT test number	629431006814
Result	✓ Passed
Next expiry date	2024-05-26
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	

MOT #9	2022-05-27 15:14
MOT test number	170183316491
Result	✓ Passed
MOT #8	2021-05-19 09:36

MOT #8	2021-05-19 09:36
MOT test number	739207805469
Result	✓ Passed

MOT #7	2020-07-11 08:51
MOT test number	565325065502

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush (5.3.4 (a) (i))

Advice Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush (5.3.4 (a) (i))

CarCheck.co.uk page 3/11



MOT #2

Result

MOT test number

RK130CU

report date: 2024-03-29

2017-01-17 14:55

526094219998

✓ Passed

MOT #6	2019-02-15 08:31
MOT test number	840932383949
Result	✓ Passed
MOT #5	2019-02-13 14:24
MOT test number	932599220274
Result	× Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MOT #4	2018-02-16 12:03
MOT test number	651556573065
Result	✓ Passed
MOT #3	2017-03-20 12:02
MOT test number	196678783988
Result	✓ Passed

MOT #1	2016-03-02 13:20
MOT test number	154510586236
Result	✓ Passed

CarCheck.co.uk page 4/11



RK13OCU report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	26 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



RK130CU

report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



RK130CU

report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
THE STATE OF THE S	

THE PARTY OF THE P	

	More info >
	More into >
Plate changes	
See in this check if this MINI had different number plates.	
Womber of clotes	
Municipal of pratein	
Current registration	NE NE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



RK130CU

report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-19
Last registration	2023-05-02
Complete history	See info



Registration #1	2013-03-19	22 mi
Registration #2	2016-03-02	20.819 mi
Registration #3	2017-01-17	30.992 mi
Registration #4	2017-03-20	31.277 mi
Registration #5	2018-02-16	32.587 mi
Registration #6	2019-02-13	37.657 mi
Registration #7	2019-02-15	37.667 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3758 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4 page 13	1/11

Number of axles2Engine numberA024J401