



WRO7TUA

report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO CARGO 16V MULTIJET SX
Colour	Blue
Year of manufacture	-
Top speed	91 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel



**MOT history**

MOT #17	2020-10-05 15:44
MOT test number	191896593537
Result	✓ Passed
Next expiry date	2021-10-04
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16	2020-10-05 15:44
MOT test number	707850646593
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15	2020-01-10 12:59
MOT test number	775527238451
Result	✓ Passed

MOT #14	2020-01-10 12:59
MOT test number	440499078913
Result	✗ Failed
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #13	2018-09-13 10:36
MOT test number	192484304412
Result	✓ Passed
Advice	Leak at steering rack
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #12	2017-06-01 15:43
MOT test number	506514608366
Result	✓ Passed
MOT #11	2016-05-17 14:46
MOT test number	538458498424
Result	✓ Passed
MOT #10	2015-05-28 14:59
MOT test number	885078245186
Result	✓ Passed
MOT #9	2014-06-10 09:59
MOT test number	126381864100
Result	✓ Passed
MOT #8	2013-06-06 12:42
MOT test number	895467853131
Result	✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Parking brake lever has little reserve travel (3.1.6b)

**MOT #7** 2013-06-05 16:12**MOT test number** 489166953184**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #6 2012-05-31 15:00**MOT test number** 968422152193**Result** ✓ Passed**MOT #5** 2012-05-31 15:00**MOT test number** 237592752482**Result** ✗ Failed

- Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #4** 2011-06-10 09:52**MOT test number** 176451361105**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

MOT #3 2011-06-07 12:28**MOT test number** 267758851456**Result** ✗ Failed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** The front wheels appear to be badly misaligned due to the damaged offside inner steering arm.
- Fail** Offside Inner Front Steering arm damaged and unserviceable (2.2.C.1d)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Pass with rectification** Offside Headlamp aim too low (1.8)

MOT #2 2010-04-16 12:14**MOT test number** 203666700183**Result** ✓ Passed**MOT #1** 2010-04-15 16:20**MOT test number** 643685600136**Result** ✗ Failed

- Fail** Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-04-27
Last registration	2020-10-05
Complete history	See info



Registration #1	2007-04-27	22 mi
Registration #2	2010-04-15	27.699 mi
Registration #3	2010-04-16	27.700 mi
Registration #4	2011-06-07	38.844 mi
Registration #5	2011-06-10	38.850 mi
Registration #6	2012-05-31	49.916 mi
Registration #7	2013-06-05	62.187 mi
Registration #8	2013-06-06	62.242 mi
Registration #9	2014-06-10	73.714 mi
Registration #10	2015-06-10	85.186 mi
Registration #11	2016-06-10	96.658 mi
Registration #12	2017-06-10	108.130 mi
Registration #13	2018-06-10	119.602 mi
Registration #14	2019-06-10	131.074 mi
Registration #15	2020-06-10	142.546 mi
Registration #16	2021-06-10	154.018 mi
Registration #17	2022-06-10	165.490 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Number of axles	2
Engine number	NOT KNOWN