





report date: 2024-03-29

General information

Make	FORD
Model	ESCORT 1.6I 16V GHIA
Colour	Brown
Year of manufacture	1996
Top speed	108 mph
Gearbox	1 speed automatic

Engine & fuel consumption

Power	89 BHP
Max. torque	134 Nm at 3.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.0 mpg
Consumption extra urban	40.9 mpg
Consumption combined	31.7 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-30

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



N83ESN report date: 2024-03-29

MOT history

Advice

Minor

MOT expiry date	2025-04-13
MOT pass rate	94 %
MOT passed	17
Failed MOT tests	1
Total advice items	26
Total items failed	1

MOT #18	2024-04-12 11:34
MOT test number	300535094063
Result	✓ Passed
Next expiry date	2025-04-13
Advice Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))	

MOT #17	2023-04-14 09:59
MOT test number	542313580436
Result	✓ Passed
MOT #16	2022-04-09 07:46
MOT test number	596120071227
Result	✓ Passed
MOT #15	2021-02-12 13:27
MOT test number	245990596919
Result	✓ Passed
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

CarCheck.co.uk page 3/12

Rear Service brake binding but not excessively Both (1.2.1 (f))

Windscreen wiper blade defective Both (3.4 (b) (i))



report date: 2024-03-29

MOT test number

Fesult

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #13

MOT test number

609991656672

Result

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #12

MOT test number

647479295186

Result

Notice Slight bind o/s/r brake

Notice Some lift in steering column

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Some state of the state of

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #10	2013-07-19 09:37
MOT test number	917450103242
Result	✓ Passed
Notice Nearside front tyre worn on outer edge	

MOT #9	2012-07-16 17:04
MOT test number	306008892110
Result	✓ Passed
Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)	

MOT #8		2011-07-15 09:56
MOT test	number	167416291195
Result		✓ Passed
Notice	Rear brake pipes slightly rusty	
Notice	Slight rust under car	

MOT #7	2010-07-16 10:06
MOT test number	942907590122
Result	✓ Passed
Advice Vehicle structure has slight corrosion (6.1.A.1)	

MOT #6	2009-07-13 16:10
MOT test number	203564299415
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT test number

S52644199126

Result

Kentre Exhaust has a major leak of exhaust gases (7.1.2)

Notice Exhaust System Rusting

Notice Chips In Windscreen

Notice Slight Engine Oil Leaks

MOT #4 2008-07-18 12:32 **MOT** test number 674010608204 Result ✓ Passed **MOT** #3 2007-07-05 10:35 **MOT** test number 234566487490 Result ✓ Passed **Notice** Slight noise from nearside and offside rear wheel bearings Notice Nearside and offside rear suspension dust gaiters split and lose Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2 2006-07-13 13:06

MOT test number 162934096103

Result ✓ Passed

 MOT #1
 2005-07-11 16:56

 MOT test number
 213872195189

 Result
 ✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)


Notice Air bag warning lamp staying on

CarCheck.co.uk page 6/12



report date: 2024-03-29

Tax & MOT check



Days left 277

MOT expiry date 13 April 2025

Full MOT history See MOT history

CarCheck.co.uk page 7/12



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



N83ESN report date: 2024-03-29

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

HERENES .	

	More info >
	,
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	9
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	1996-04-01
Last registration	2024-04-12
Complete history	See info



Registration #1	1996-04-01	6 mi
Registration #2	2005-07-11	44.362 mi
Registration #3	2006-07-13	45.094 mi
Registration #4	2007-07-05	45.859 mi
Registration #5	2008-07-18	46.419 mi
Registration #6	2009-07-13	46.763 mi
Registration #7	2009-07-13	46.763 mi
Registration #8	2010-07-16	47.072 mi
Registration #9	2011-07-15	47.415 mi
Registration #10	2012-07-16	47.642 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	******
Video	see crash video



Additional information

Number of axles	2
Engine number	TA95794

CarCheck.co.uk page 12/12