



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 SE (170BHP)
Colour	Blue
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	225 Nm at 4.500 rpm
Cylinders	5
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	38.7 mpg
Consumption combined	30.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-12
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #18	2022-11-07 12:05
MOT test number	887368648453
Result	✓ Passed
Next expiry date	2023-11-06

MOT #17	2021-09-09 09:19
MOT test number	622387356309
Result	✓ Passed

MOT #16	2021-07-01 10:27
MOT test number	144641939223
Result	✓ Passed

MOT #15	2020-09-11 08:29
MOT test number	256119875725
Result	✓ Passed

- Advice** Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Headlamp reflector slightly defective (4.1.1 (b) (i))

MOT #14	2019-09-10 07:57
MOT test number	732965464246
Result	✓ Passed

MOT #13	2018-09-12 08:37
MOT test number	256935290670
Result	✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #12

2017-09-18 10:53

MOT test number

196662622802

Result

✓ Passed

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Advice

Offside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice

Offside Front Tyre worn close to the legal limit very near (4.1.E.1)

MOT #11

2016-09-22 07:34

MOT test number

848668232595

Result

✓ Passed

Advice

Rear Direction indicator slightly discoloured both (1.4.A.2f)

Advice

Undertray fitted

Advice

Nearside Front tyre has side wall damage but cord not exposed

MOT #10

2015-09-23 15:01

MOT test number

896635295128

Result

✓ Passed

Advice

Nearside Front Road wheel slightly damaged (4.2.A.1a)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2015-09-22 11:47**MOT test number** 794908462090**Result** ✗ Failed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #8** 2014-09-15 11:11**MOT test number** 337478154482**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #7** 2013-09-04 09:09**MOT test number** 158377543245**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-09-22 11:20**MOT test number** 369606562412**Result** ✓ Passed**MOT #5** 2012-09-22 09:29**MOT test number** 347066062486**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



MOT #4	2011-09-24 11:30
MOT test number	508927461271
Result	✓ Passed
MOT #3	2010-09-18 10:27
MOT test number	562201160238
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #2	2009-10-01 09:19
MOT test number	594144679221
Result	✓ Passed
MOT #1	2008-09-25 09:41
MOT test number	232389668214
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-09-09
Last registration	2022-11-07
Complete history	See info



Registration #1	2005-09-09	22 mi
Registration #2	2008-09-25	7.638 mi
Registration #3	2009-10-01	8.522 mi
Registration #4	2010-09-18	13.998 mi
Registration #5	2011-09-24	29.926 mi
Registration #6	2012-09-22	45.592 mi
Registration #7	2012-09-22	45.597 mi
Registration #8	2013-09-04	55.097 mi
Registration #9	2014-09-15	57.581 mi
Registration #10	2015-09-22	60.448 mi
Registration #11	2016-09-22	60.448 mi
Registration #12	2016-09-22	60.448 mi
Registration #13	2016-09-22	60.448 mi
Registration #14	2016-09-22	60.448 mi
Registration #15	2016-09-22	60.448 mi
Registration #16	2016-09-22	60.448 mi
Registration #17	2016-09-22	60.448 mi
Registration #18	2016-09-22	60.448 mi
Registration #19	2016-09-22	60.448 mi
Registration #20	2016-09-22	60.448 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1720 mm
Height	1400 mm
Length	4520 mm
Wheel base	2560 mm
Kerb weight	1485 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	3645005