



report date: 2024-03-29

## General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Black
Year of manufacture	2009
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-11-01
Pictures	3
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-11-19
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	17
Total items failed	3

MOT #16	2023-11-20 13:54
MOT test number	825499101498
Result	✓ Passed
Next expiry date	2024-11-19

MOT #15	2022-11-09 14:05
MOT test number	364763938162
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

MOT #14	2021-11-03 17:00
MOT test number	842662947419
Result	✓ Passed
Minor	Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened all 4 (1.1.14 (a) (ii))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides - rear bushes (5.3.4 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2020-08-21 10:44

**MOT test number**

374840460376

**Result**

✓ Passed

**Minor**

Nearside Front Drive shaft joint constant velocity boot severely deteriorated outer (6.1.7 (g) (i))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Chip in windscreen

**Advice**

Tpms on

**Advice**

(i)) Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a))

**MOT #12**

2019-05-10 14:46

**MOT test number**

562714040528

**Result**

✓ Passed

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #11**

2018-04-26 12:16

**MOT test number**

707346430611

**Result**

✓ Passed

**Advice**

Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice**

Front Tyre worn close to the legal limit nearside , offside (4.1.E.1)

**MOT #10**

2017-05-10 15:30

**MOT test number**

395212270234

**Result**

✓ Passed

**MOT #9**

2017-05-10 14:19

**MOT test number**

119537950439

**Result**

✗ Failed

**Fail**

Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #8** 2016-11-18 12:23**MOT test number** 955520851466**Result** ✓ Passed**Advice** Nearside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #7** 2015-11-06 12:21**MOT test number** 422319548309**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2014-10-27 08:50**MOT test number** 406570204367**Result** ✓ Passed**MOT #5** 2014-05-19 14:28**MOT test number** 816239834158**Result** ✓ Passed**MOT #4** 2014-05-16 16:37**MOT test number** 975706034120**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2013-05-15 16:56**MOT test number** 957665633169**Result** ✓ Passed



MOT #2	2012-05-18 12:41
MOT test number	227629432142
Result	✓ Passed

MOT #1	2012-05-16 16:22
MOT test number	925677732169
Result	✗ Failed

**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
19 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	19 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>LS09VRE</b>
Plate since	2024-03-29
Current registration	 <b>LS09VRE</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-05-16
Last registration	2023-11-20
Complete history	<a href="#">See info</a>



Registration #1	2009-05-16	17 mi
Registration #2	2012-05-16	9.525 mi
Registration #3	2012-05-18	9.525 mi
Registration #4	2013-05-15	12.904 mi
Registration #5	2014-05-16	16.582 mi
Registration #6	2014-05-19	16.582 mi
Registration #7	2014-10-27	17.822 mi
Registration #8	2015-11-06	22.951 mi
Registration #9	2016-11-18	28.839 mi
Registration #10	2016-11-18	28.839 mi
Registration #11	2016-11-18	28.839 mi
Registration #12	2016-11-18	28.839 mi
Registration #13	2016-11-18	28.839 mi
Registration #14	2016-11-18	28.839 mi
Registration #15	2016-11-18	28.839 mi
Registration #16	2016-11-18	28.839 mi
Registration #17	2016-11-18	28.839 mi
Registration #18	2016-11-18	28.839 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

W6129009