



report date: 2024-03-29

General information

Make	MAZDA
Model	CX-5 D SE-L NAV 4WD
Colour	Red
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 1.800 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	57.6 mpg
Consumption combined	51.4 mpg
CO2 emission	144 g/km
CO2 label	F





MOT history

MOT expiry date	2024-07-30
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	20
Total items failed	8

MOT #10	2023-07-31 10:12
MOT test number	810709483077
Result	✓ Passed
Next expiry date	2024-07-30
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9	2023-07-31 10:12
MOT test number	442677695534
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #8**

2023-07-29 13:19

MOT test number

423399948399

Result**✗ Failed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak under engine**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #7**

2022-06-20 13:30

MOT test number

275470991350

Result**✓ Passed****Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #6** 2022-06-18 11:42**MOT test number** 280079189879**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Drag link end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #5** 2021-12-22 13:56**MOT test number** 896125606106**Result** ✓ Passed**MOT #4** 2021-07-02 13:18**MOT test number** 519385459142**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #3** 2017-09-20 11:14**MOT test number** 292902458126**Result** ✓ Passed



MOT #2	2017-07-31 14:14
MOT test number	427133484097
Result	✗ Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #1	2016-05-13 11:13
MOT test number	719210033240
Result	✓ Passed
Advice	Both front tyres unevenly wearing



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
30 July 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	30 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-06-03
Last registration	2023-07-31
Complete history	See info



Registration #1	2013-06-03	16 mi
Registration #2	2016-05-13	81.902 mi
Registration #3	2017-07-31	99.758 mi
Registration #4	2017-09-20	103.109 mi
Registration #5	2021-07-02	110.703 mi
Registration #6	2021-12-22	111.596 mi
Registration #7	2023-07-31	111.596 mi
Registration #8	2023-07-31	111.596 mi
Registration #9	2023-07-31	111.596 mi
Registration #10	2023-07-31	111.596 mi
Registration #11	2023-07-31	111.596 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	87%
Pedestrian	64%
Safety systems	86%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1670 mm
Length	4540 mm
Wheel base	2700 mm
Kerb weight	1540 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30279274