



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	CLS CLS320 CDI
Colour	Silver
Year of manufacture	2009
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	27.7 mpg
CO2 emission	215 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-01-24
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-18
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	16
Total items failed	7

MOT #16	2024-01-15 16:23
MOT test number	154730176659
Result	✓ Passed
Next expiry date	2025-01-18

MOT #15	2023-01-19 14:10
MOT test number	849767200216
Result	✓ Passed

MOT #14	2022-09-02 08:33
MOT test number	751878934440
Result	✓ Passed

MOT #13	2021-09-03 06:40
MOT test number	694407815129
Result	✓ Passed

MOT #12	2020-09-04 15:46
MOT test number	507376220525
Result	✓ Passed



MOT #11	2019-09-06 08:53
MOT test number	369669371965
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #10	2019-09-06 08:53
MOT test number	565163465496
Result	✗ Failed
Pass with rectification	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Pass with rectification	Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #9	2018-09-06 12:44
MOT test number	465137491389
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2018-09-05 08:18**MOT test number** 134209988293**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7** 2017-08-09 11:20**MOT test number** 375283592954**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2016-08-26 16:35**MOT test number** 198411069898**Result** ✓ Passed**MOT #5** 2015-09-02 12:07**MOT test number** 839615645252**Result** ✓ Passed**MOT #4** 2014-08-12 12:08**MOT test number** 156174224208**Result** ✓ Passed

**MOT #3** 2013-08-20 14:53**MOT test number** 396112333245**Result** ✓ Passed**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Steering column top bearing slightly worn (2.1.2c)**Advice** Offside Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #2** 2013-08-20 14:53**MOT test number** 675322533211**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too far to the right (1.8)**Advice** Offside Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Pass with rectification** Nearside Front Headlamp aim too far to the right (1.8)**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Steering column top bearing slightly worn (2.1.2c)**MOT #1** 2012-08-14 12:10**MOT test number** 446527522272**Result** ✓ Passed**Notice** NSF tyre starting to crack on inner sidewall.



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
18 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-04
Last registration	2024-01-15
Complete history	See info



Registration #1	2009-09-04	28 mi
Registration #2	2012-08-14	17.958 mi
Registration #3	2013-08-20	24.688 mi
Registration #4	2014-08-12	29.928 mi
Registration #5	2015-09-02	37.164 mi
Registration #6	2016-08-26	44.152 mi
Registration #7	2017-08-09	49.025 mi
Registration #8	2018-09-05	52.911 mi
Registration #9	2018-09-06	52.911 mi
Registration #10	2019-09-02	55.277 mi
Registration #11	2019-09-02	55.277 mi
Registration #12	2019-09-02	55.277 mi
Registration #13	2019-09-02	55.277 mi
Registration #14	2019-09-02	55.277 mi
Registration #15	2019-09-02	55.277 mi
Registration #16	2019-09-02	55.277 mi
Registration #17	2019-09-02	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm
Kerb weight	1815 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	64292040790416