





report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO 625 ENTERPRISE L1 BLUEHDI
Colour	White
Year of manufacture	2016
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-20

Pictures 14

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-12-13	
MOT pass rate	63 %	
MOT passed	5	
Failed MOT tests	3	
Total advice items	17	
Total items failed	11	

MOT #8		2023-12-04 10:30
MOT test	number	949499986898
Result		✓ Passed
Next expi	ry date	2024-12-13
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7		2022-12-07 15:49
MOT test	number	601668952351
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin rear brake pads (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #6 2022-12-07 10:10 **MOT** test number 404686783091 Result × Failed **Advice** Rear Brake pad(s) wearing thin rear brake pads (1.1.13 (a) (ii)) Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii)) Fail Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge down to 3mm (5.2.3 (e))

Advice Outer Spare tyre defective spare tyre flat


Advice Nearside Front Tyre worn close to legal limit/worn on edge down to 3mm (5.2.3 (e))

MOT #4	2020-11-17 15:20
MOT test number	846701176484
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28



MOT #2		2019-12-09 09:52
MOT test	number	604659561479
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Nail in tyre	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Upper Oil leak, but not excessive from engine (8.4.1 (a) (i))	

CarCheck.co.uk page 5/13



report date: 2024-03-28

2019-12-09 09:52 **MOT #1** 530746059931 **MOT test number** Result × Failed **Advice** Nearside Rear Nail in tyre Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Pass with rectification Offside Rear Brake cable insecure (1.1.15 (c)) Pass with rectification Central Front Seat belt buckle missing (7.1.2 (d)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Front Upper Oil leak, but not excessive from engine (8.4.1 (a) (i))

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

\sim	wn		- L	4۔:		
	Mη	ല	n	IST	n	r١

,		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-12-14
Last registration	2023-12-04
Complete history	See info



Registration #1	2016-12-14	23 mi
Registration #2	2019-12-09	46.835 mi
Registration #3	2019-12-09	46.835 mi
Registration #4	2020-11-16	61.088 mi
Registration #5	2020-11-17	61.089 mi
Registration #6		0.00 44
		11.777 ea 11.777 ea
Registration #6		11.777 ea 11.777 ea 11.777 ea
Registration #6 Registration #7		11,777-00 11,777-00 11,777-00

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	***
Adult	56%
Children	74%
Pedestrian	63%
Safety systems	48%
Overall rating	59%
Video	see crash video

Dimensions & weight

Width	2112 mm
Height	1801 mm
Length	4380 mm
Kerb weight	1309 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBHB3123865

CarCheck.co.uk page 13/13