



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 T S S60
Colour	Blue
Year of manufacture	2001
Top speed	130 mph
0 - 60 mph	9.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	177 BHP
Max. torque	240 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	37.7 mpg
Consumption combined	28.0 mpg
CO2 emission	242 g/km
CO2 label	L





MOT history

MOT expiry date	2021-09-09
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	38
Total items failed	17

MOT #24 2020-08-22 11:45

MOT test number 198562269154

Result ✓ Passed

Next expiry date 2021-09-09

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Minor Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #23 2019-08-24 12:31

MOT test number 870560356776

Result ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #22 2019-08-24 12:31

MOT test number 556461141654

Result ✗ Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #21** 2018-09-08 10:42**MOT test number** 829362321156**Result** ✓ Passed**Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))**MOT #20** 2017-08-26 14:31**MOT test number** 185590635286**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Exhaust emits blue smoke during acceleration (7.3.A.2c)**MOT #19** 2017-08-26 09:48**MOT test number** 339713000888**Result** ✗ Failed**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Exhaust emits blue smoke during acceleration (7.3.A.2c)**MOT #18** 2016-09-10 15:09**MOT test number** 692200299902**Result** ✓ Passed**MOT #17** 2015-09-08 16:57**MOT test number** 858495652549**Result** ✓ Passed



MOT #16	2015-09-08 11:28
MOT test number	982958971350
Result	✗ Failed
Fail	Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

MOT #15	2014-09-02 16:28
MOT test number	338555644438
Result	✓ Passed

MOT #14	2014-09-02 16:28
MOT test number	477755244270
Result	✗ Failed
Pass with rectification	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
Pass with rectification	Offside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #13	2013-08-23 17:46
MOT test number	379045233295
Result	✓ Passed
Advice	Nearside Brake hose slightly deteriorated (3.6.B.4d)
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Offside Front Brake hose slightly deteriorated (3.6.B.4d)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #12**

2012-09-03 17:38

MOT test number

317307942271

Result

✓ Passed

Advice Nearside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #11

2012-09-03 16:52

MOT test number

757327342259

Result

✗ Failed

Fail Nearside Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #10

2011-09-06 15:28

MOT test number

857389141219

Result

✓ Passed

Advice Offside Inner Ball joint has slight play (2.2.B.1f)

Advice Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

Notice Rear exhaust bracket broken

Advice Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)



MOT #9	2010-08-06 10:59
MOT test number	234718910294
Result	✓ Passed
Notice	ENGINE MAY BE LEAKING OIL

MOT #8	2010-08-06 10:59
MOT test number	983718010281
Result	✗ Failed
Notice	ENGINE MAY BE LEAKING OIL
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)

MOT #7	2009-08-07 10:05
MOT test number	820379519262
Result	✗ Failed
Pass with rectification	Rear registration plate delaminated (6.3.1d)
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Notice	NSR TYRE TREAD IS WORN VERY CLOSE TO THE LEGAL MIN
Pass with rectification	Front registration plate letter/figure incomplete (6.3.1c)
Notice	NS NUMBER PLATE LAMP IS DULL AND MAY NEED A NEW BULB
Pass with rectification	Rear registration plate letter/figure incomplete (6.3.1c)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)
Notice	BOTH FRONT TYRE TREAD ARE STARTING TO GET LOW
Pass with rectification	Front registration plate delaminated (6.3.1d)

**MOT #6** 2009-08-07 10:05**MOT test number** 713359219255**Result** ✓ Passed

- Notice** BOTH FRONT TYRE TREAD ARE STARTING TO GET LOW
- Notice** NSR TYRE TREAD IS WORN VERY CLOSE TO THE LEGAL MIN
- Notice** NS NUMBER PLATE LAMP IS DULL AND MAY NEED A NEW BULB

MOT #5 2008-08-29 14:01**MOT test number** 741322048247**Result** ✗ Failed

- Advice** Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Notice** Front and rear number plates poor
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2008-08-29 14:01**MOT test number** 862872048225**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Notice** Front and rear number plates poor

MOT #3 2007-09-01 11:49**MOT test number** 712154447256**Result** ✓ Passed

- Notice** NS NUMBER PLATE IS DULL



MOT #2	2006-08-25 09:00
MOT test number	783027736252
Result	✓ Passed

MOT #1	2006-08-25 09:00
MOT test number	174257936255
Result	✗ Failed
<div>Pass with rectification</div> Offside Front position lamp(s) not working (1.1.A.3b)	



Tax & MOT check

✕
Untaxed

Tax expired:
15 December 2020

✕
MOT

Expired:
9 September 2021

Tax status	Expired at 15 December 2020
Days left	1232 days too late
MOT expiry date	9 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	Y473YGH
Plate since	2024-03-29
Current registration	Y473YGH
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2001-03-30
Last registration	2020-08-22
Complete history	See info



Registration #1	2001-03-30	9 mi
Registration #2	2006-08-25	71.011 mi
Registration #3	2007-09-01	80.721 mi
Registration #4	2008-08-29	91.450 mi
Registration #5	2009-08-07	100.471 mi
Registration #6	2010-08-06	109.455 mi
Registration #7	2011-09-06	119.671 mi
Registration #8	2012-09-03	127.016 mi
Registration #9	2012-09-03	127.016 mi
Registration #10	2013-08-23	135.543 mi
Registration #11	2014-08-23	144.074 mi
Registration #12	2015-08-23	152.605 mi
Registration #13	2016-08-23	161.136 mi
Registration #14	2017-08-23	169.667 mi
Registration #15	2018-08-23	178.198 mi
Registration #16	2019-08-23	186.729 mi
Registration #17	2020-08-22	195.260 mi
Registration #18	2021-08-22	203.791 mi
Registration #19	2022-08-22	212.322 mi
Registration #20	2023-08-22	220.853 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1803 mm
Height	1422 mm
Length	4572 mm
Wheel base	2715 mm
Kerb weight	1427 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	2494881