



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRTD CDX
Colour	Black
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	335 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.0 mpg



LABEL UNKNOWN



MOT history

MOT #18	2020-12-23 16:26
MOT test number	189413575656
Result	✓ Passed
Next expiry date	2021-12-22

MOT #17	2019-11-13 12:40
MOT test number	115029232481
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2019-11-12 12:07
MOT test number	263355974260
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
DANGEROUS	Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Rear Brake pad(s) wearing thin Both rear (1.1.13 (a) (ii))
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
DANGEROUS	Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2018-11-15 12:22
MOT test number	514332686822
Result	✓ Passed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #14**

2018-11-14 14:20

MOT test number

738836157835

Result**✗ Failed**

- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Central Rear Obligatory mirror insecure (3.3 (b) (ii))

MOT #13

2016-12-06 09:49

MOT test number

640472847198

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #12

2015-07-28 10:39

MOT test number

855139805222

Result**✓ Passed**

- Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)
- Notice** Oil leak
- Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Notice** Eml light on
- Advice** Offside Side repeater slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)

**MOT #11**

2015-07-28 10:39

MOT test number

756109205270

Result**✗ Failed****Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Notice** Oil leak**Pass with rectification** Nearside Outer Rear Stop lamp not working (1.2.1b)**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)**Notice** Eml light on**Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)**MOT #10**

2014-07-22 09:10

MOT test number

329053904221

Result**✓ Passed****Notice** Nail in offside front tyre**MOT #9**

2014-07-22 09:10

MOT test number

365353504439

Result**✗ Failed****Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Headlamp has a product on the light source so that the light output is severely reduced (1.7.5a)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Notice** Nail in offside front tyre**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #8** 2013-07-23 10:48**MOT test number** 619444603236**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside front tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2012-07-30 12:31**MOT test number** 136572712240**Result** ✓ Passed**MOT #6** 2012-07-30 12:31**MOT test number** 597782112242**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2011-07-09 11:06**MOT test number** 899290791136**Result** ✓ Passed**MOT #4** 2010-07-07 15:09**MOT test number** 954468880190**Result** ✓ Passed**MOT #3** 2009-07-10 11:41**MOT test number** 442701199115**Result** ✓ Passed



MOT #2	2008-07-11 13:40
MOT test number	174923198116
Result	✓ Passed

MOT #1	2007-07-11 16:48
MOT test number	213262597485
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-07-14
Last registration	2020-12-23
Complete history	See info



Registration #1	2006-07-14	27 mi
Registration #2	2007-07-11	28.328 mi
Registration #3	2008-07-11	47.406 mi
Registration #4	2009-07-10	62.369 mi
Registration #5	2010-07-07	76.234 mi
Registration #6	2011-07-09	90.124 mi
Registration #7	2012-07-30	101.197 mi
Registration #8	2013-07-23	106.578 mi
Registration #9	2014-07-20	111.959 mi
Registration #10	2015-07-19	117.340 mi
Registration #11	2016-07-18	122.721 mi
Registration #12	2017-07-17	128.102 mi
Registration #13	2018-07-16	133.483 mi
Registration #14	2019-07-15	138.864 mi
Registration #15	2020-07-14	144.245 mi
Registration #16	2021-07-13	149.626 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1725 mm
Length	4650 mm
Wheel base	2700 mm
Kerb weight	1853 kg
Max. allowed weight	2550 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4EB6936091