





General information

Make	ΤΟΥΟΤΑ
Model	IQ VVT-I IQ
Colour	Red
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

	ē	
Power	67 BHP	0 < 101 A
Max. torque	91 Nm at 4.800 rpm	101 - 120 B
Engine capacity	998 cc	121 - 140 P
Cylinders	3	141 - 165 F
uel type	Petrol	166 - 185
Consumption city	57.7 mpg	186 - 225
onsumption extra urban	72.4 mpg	225+
Consumption combined	65.7 mpg	
CO2 emission	99 g/km	
CO2 label	А	





Internet history	
Entry 1	
Date	2022-02-17
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-14
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	21
Total items failed	5

MOT #17	2024-03-07 08:27
MOT test number	637860891330
Result	✓ Passed
Next expiry date	2025-03-14

MOT #16	2023-03-10 11:21
MOT test number	965252202463
Result	✓ Passed

MOT #15	2022-03-15 16:31
MOT test number	232774489664
Result	✓ Passed

MOT #14	2021-08-24 09:29
MOT test number	179372085376
Result	🗸 Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2020-09-10 10:37
MOT test number	345134332321
Result	✓ Passed





MOT #12	2020-09-10 09:29
MOT test number	662494999761
Result	🗙 Failed
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b)	o) (ii))
MOT #11	2019-08-28 16:31
MOT test number	714952005607
Result	✓ Passed
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice Offside Rear Tyre worn close to legal limit/worn on edge Close to limit 1.9mm (5.2.3 (e))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MOT #10	2019-08-28 07:28

	2019-00-20 07.20
MOT test number	999531490333
Result	🗙 Failed
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice Offside Rear Tyre worn close to legal limit/worn on edge Close to limit 1.9m	ım (5.2.3 (e))





MOT #9	202	18-09-04 08:59
MOT test	number	742263669234
Result		🗸 Passed
Advice	Rear Unable to check rear seat belts, seats folded down when vehicle presented for t	est.
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Tread on 2mm. (5.2.3 (e))	
Advice	Offside Front Tyre valve cracked/perished.	

MOT #8		2017-08-23 14:42
MOT test	number	399729097313
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2016-08-30 14:20
MOT test number	737428067802
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #6	2015-08-26 00:00
MOT test number	805376035586
Result	✓ Passed
Advice Tyre worn close to the legal limit Both front & N/S/R (4.1.E.1)	

MOT #5	2014-09-05 15:34
MOT test number	158198144241
Result	🗸 Passed
Notice O/s/f tyre valve stem deteriorated (cracking)	





MOT #4	2013-09-09 16:46
MOT test number	547382853225
Result	✓ Passed
Notice Both front wipers torn	
MOT #3	2013-09-09 14:35
MOT test number	179762153276
Result	🗙 Failed
Fail Nearside Headlamp aim too low (1.8)	
Notice Both front wipers torn	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #2	2012-09-13 13:57
MOT test number	547307052287
Result	✓ Passed

MOT #1	2012-09-13 13:57
MOT test number	578437352200
Result	× Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

Tax due: 1 March 2025	✓ Taxed	Expires: 14 March 2025	✓ мот
Tax status			Valid until 1 March
Days left			307
MOT expiry date			14 March 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		48	

	10
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETO
Category	Lamp
Туре	
Damage 2	AMPL
Date	Nº I
Category	ANNY.
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 11.111
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates	
Number of plates	,
Current registration	
Plate since	
Correct registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-04
Last registration	2024-03-07
Complete history	See info



Registration #1	2009-09-04	22 mi
Registration #2	2012-09-13	17.426 mi
Registration #3	2013-09-09	21.724 mi
Registration #4	2013-09-09	21.724 mi
Registration #5	2014-09-05	27.853 mi
Registration #6	2015-08-26	32.669 mi
Registration #7	2016-08-30	37.921 mi
Registration #8	2017-08-23	43.487 mi
Registration #9	2018-09-04	49.404 mi
Registration #10		11.777 esi
Registration #11		11.777 est
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 esi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg
Additional information	
Fuel tank capacity	32
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	1KR0827053