



RY05BCV


report date: 2024-03-28

General information

Make	JAGUAR
Model	XJ V8 SPORT
Colour	Black
Year of manufacture	2005
Top speed	150 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	262 BHP
Max. torque	344 Nm at 4.200 rpm
Engine capacity	3.555 cc
Cylinders	8
Fuel type	Petrol
Consumption city	17.8 mpg
Consumption extra urban	36.7 mpg
Consumption combined	26.4 mpg
CO2 emission	254 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-07-13
Pictures	29
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-20
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	21
Total items failed	15

MOT #19	2023-07-21 10:21
MOT test number	580280685293
Result	✓ Passed
Next expiry date	2024-07-20
Advice	Nearside Rear Nail in tyre
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #18	2022-07-13 09:39
MOT test number	356632439649
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17**

2022-06-29 09:49

MOT test number

844678982763

Result**✗ Failed****Advice** Nearside Front Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Suspension arm pin or bush excessively worn inner bush (5.3.4 (a) (i))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Rear Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt outer bush (5.3.4 (b) (ii))**Fail** Nearside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Suspension arm ball joint dust cover no longer prevents the ingress of dirt inner and outer (track control arm) (5.3.4 (b) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Lower Suspension arm pin or bush excessively worn inner bush (5.3.4 (a) (i))**Advice** Offside Front Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt outer bush (5.3.4 (b) (ii))**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Suspension arm ball joint dust cover no longer prevents the ingress of dirt inner and outer (track control arm) (5.3.4 (b) (ii))**MOT #16**

2021-07-08 09:48

MOT test number

177666378461

Result**✓ Passed**

**MOT #15** 2020-11-24 11:55**MOT test number** 835233390451**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 235/50/18 (5.2.3 (d) (ii))**MOT #14** 2019-06-27 14:49**MOT test number** 923214293344**Result** ✓ Passed**MOT #13** 2018-06-05 12:57**MOT test number** 275900359549**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2017-06-15 12:44**MOT test number** 628199671353**Result** ✓ Passed**MOT #11** 2016-06-27 07:43**MOT test number** 498882118638**Result** ✓ Passed**MOT #10** 2016-06-27 07:43**MOT test number** 661715880280**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)

**MOT #9** 2015-07-01 11:01**MOT test number** 107742985106**Result** ✓ Passed**MOT #8** 2015-06-24 09:12**MOT test number** 747155575190**Result** ✗ Failed

- Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)
- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #7 2014-07-18 16:05**MOT test number** 436109194133**Result** ✓ Passed**MOT #6** 2013-05-29 10:09**MOT test number** 249379743178**Result** ✓ Passed**MOT #5** 2012-05-29 14:59**MOT test number** 477330252104**Result** ✓ Passed**MOT #4** 2011-06-01 11:58**MOT test number** 238312451137**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2010-06-03 13:41
MOT test number	784014050193
Result	✓ Passed
MOT #2	2009-05-19 11:00
MOT test number	601559639170
Result	✓ Passed
MOT #1	2008-05-31 11:56
MOT test number	922372658165
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-06-06
Last registration	2023-07-21
Complete history	See info



Registration #1	2005-06-06	13 mi
Registration #2	2009-05-19	40.185 mi
Registration #3	2010-06-03	44.704 mi
Registration #4	2011-06-01	50.306 mi
Registration #5	2012-05-29	54.292 mi
Registration #6	2013-05-29	58.141 mi
Registration #7	2014-07-18	63.014 mi
Registration #8	2015-06-24	65.427 mi
Registration #9	2015-07-01	65.437 mi
Registration #10	2016-06-27	67.787 mi
Registration #11	2016-06-27	67.787 mi
Registration #12	2016-06-27	67.787 mi
Registration #13	2016-06-27	67.787 mi
Registration #14	2016-06-27	67.787 mi
Registration #15	2016-06-27	67.787 mi
Registration #16	2016-06-27	67.787 mi
Registration #17	2016-06-27	67.787 mi
Registration #18	2016-06-27	67.787 mi
Registration #19	2016-06-27	67.787 mi
Registration #20	2016-06-27	67.787 mi

More info >



Dimensions & weight

Width	1480 mm
Height	1448 mm
Length	5090 mm
Wheel base	3034 mm
Kerb weight	1615 kg
Max. allowed weight	2231 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0503160623RB