



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO 2700 L1H1 CDTi P/V
Colour	White
Year of manufacture	2016
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	42.8 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 2


Date	2022-10-27
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-19
Pictures	36
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-11-08
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #7	2023-10-23 11:10
MOT test number	381028544801
Result	✓ Passed
Next expiry date	2024-11-08
Advice	Nearside Front drl not working
Advice	Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #6	2023-10-23 11:10
MOT test number	673662710554
Result	✗ Failed
Advice	Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Pass with rectification	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Nearside Front drl not working
Pass with rectification	Steering rack has excessive free play detected at the steering wheel (steering rack fitted) (2.3 (a) (i))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Pass with rectification	Nearside Front Headlamp aim too high and too far to the right. (4.1.2 (a))

**MOT #5** 2022-11-09 15:46**MOT test number** 919382612511**Result** ✓ Passed**MOT #4** 2021-08-11 14:52**MOT test number** 308952090482**Result** ✓ Passed**MOT #3** 2021-08-11 13:47**MOT test number** 282957341867**Result** ✗ Failed

DANGEROUS Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2020-08-10 09:25**MOT test number** 872795954268**Result** ✓ Passed**MOT #1** 2019-05-15 08:11**MOT test number** 604142847006**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 November 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-05-23
Last registration	2023-10-23
Complete history	See info



Registration #1	2016-05-23	29 mi
Registration #2	2019-05-15	40.242 mi
Registration #3	2020-08-10	56.581 mi
Registration #4	2021-08-11	65.847 mi
Registration #5	2021-08-11	65.847 mi
Registration #6	2022-05-22	75.277 mi
Registration #7	2022-05-22	75.277 mi
Registration #8	2022-05-22	75.277 mi
Registration #9	2022-05-22	75.277 mi
Registration #10	2023-10-23	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	1956 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1661 kg
Max. allowed weight	2740 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	R9M MD - C101589LWZ