



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE LUX
Colour	Black
Year of manufacture	2013
Top speed	137 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-08
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-01
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #11 2023-10-30 16:28

MOT test number 458663904869

Result ✓ Passed

Next expiry date 2024-11-01

Advice Rear Brake disc worn, but not excessively both sides (1.1.14 (a) (i))**Advice** Coil spring corroded offside and nearside (5.3.1 (b) (i))

MOT #10 2023-10-14 08:30

MOT test number 820198886444

Result ✗ Failed**Advice** Rear Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (i))**Fail** Offside Front Outer Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Rear Coil spring corroded offside and nearside (5.3.1 (b) (i))**Advice** Offside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #9 2022-11-02 14:13

MOT test number 741480289801

Result ✓ Passed

**MOT #8** 2021-11-02 13:21**MOT test number** 244869708606**Result** ✓ Passed**MOT #7** 2020-10-20 09:15**MOT test number** 739126987389**Result** ✓ Passed**MOT #6** 2019-10-21 15:02**MOT test number** 763330531533**Result** ✓ Passed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (front bush) (5.3.4 (a) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (front bush) (5.3.4 (a) (i))

MOT #5 2019-10-21 13:08**MOT test number** 694409481489**Result** ✗ Failed

Advice Offside Rear Inner Tyre slightly damaged/cracking or perishing close to cord (5.2.3 (d) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (front bush) (5.3.4 (a) (i))

Fail Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (front bush) (5.3.4 (a) (i))

MOT #4 2018-10-29 10:51**MOT test number** 351375104326**Result** ✓ Passed



MOT #3	2017-10-31 15:38
MOT test number	589041447028
Result	✓ Passed
Advice	Engine and underside covers fitted not allowing full inspection
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2017-03-24 12:17
MOT test number	751536752623
Result	✓ Passed

MOT #1	2016-03-22 09:50
MOT test number	441924442453
Result	✓ Passed
Advice	Front Tyre worn close to the legal limit both front tyres inside edges (4.1.E.1)
Advice	Front Brake pad(s) wearing thin both sides (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-27
Last registration	2023-10-30
Complete history	See info



Registration #1	2013-03-27	25 mi
Registration #2	2016-03-22	45.995 mi
Registration #3	2017-03-24	55.139 mi
Registration #4	2017-10-31	62.460 mi
Registration #5	2018-10-29	72.573 mi
Registration #6	2019-10-21	80.150 mi
Registration #7	2019-10-21	80.150 mi
Registration #8	2019-10-21	80.150 mi
Registration #9	2019-10-21	80.150 mi
Registration #10	2019-10-21	80.150 mi
Registration #11	2019-10-21	80.150 mi
Registration #12	2019-10-21	80.150 mi
Registration #13	2019-10-21	80.150 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1770 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1297393