



report date: 2024-03-28

General information

| | |
|---------------------|---------------------------|
| Make | NISSAN |
| Model | QASHQAI ACENTA PLUS 2 DCI |
| Colour | Grey |
| Year of manufacture | 2008 |
| Top speed | 117 mph |
| 0 - 60 mph | 11.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 320 Nm at 4.000 rpm |
| Engine capacity | 1.994 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 31.7 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2019-11-26 |
| MOT pass rate | 89 % |
| MOT passed | 8 |
| Failed MOT tests | 1 |
| Total advice items | 12 |
| Total items failed | 10 |

| | |
|------------------|--|
| MOT #9 | 2018-11-22 10:38 |
| MOT test number | 759276857365 |
| Result | ✓ Passed |
| Next expiry date | 2019-11-26 |
| Minor | Nearside Front Inner Prop shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |

| | |
|-----------------|----------------------------|
| MOT #8 | 2017-11-27 10:55 |
| MOT test number | 348556115213 |
| Result | ✓ Passed |
| Advice | Dpf light on |
| Advice | Engine management light on |

**MOT #7** 2017-11-27 09:40**MOT test number** 652430079398**Result** ✗ Failed**Advice** Dpf light on**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Exhaust emits excessive smoke or vapour of any colour (7.4.B.4)**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Registration plate lamp insecure (1.1.C.1c)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Engine management light on**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Registration plate lamp insecure (1.1.C.1c)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2016-11-21 12:03**MOT test number** 130736414669**Result** ✓ Passed**MOT #5** 2015-10-21 09:38**MOT test number** 580116960725**Result** ✓ Passed

**MOT #4** 2014-10-24 13:06**MOT test number** 385457394280**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Nearside rear tyre worn on outer edge and low on tread**Notice** Nearside front tyre worn to 3mm**Notice** Front and rear brake pads getting low**MOT #3** 2013-10-21 15:55**MOT test number** 697804793296**Result** ✓ Passed**Notice** Offside front tyre cut in sidewall**Notice** Rear tyres worn on outer edges**Notice** Number plate light units loose**MOT #2** 2012-10-18 10:45**MOT test number** 849622192278**Result** ✓ Passed**MOT #1** 2011-10-27 11:14**MOT test number** 466150301404**Result** ✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2008-10-25 |
| Last registration | 2018-11-22 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2008-10-25 | 12 mi |
| Registration #2 | 2011-10-27 | 32.993 mi |
| Registration #3 | 2012-10-18 | 38.049 mi |
| Registration #4 | 2013-10-21 | 43.702 mi |
| Registration #5 | 2014-10-24 | 49.164 mi |
| Registration #6 | 2015-10-27 | 55.277 mi |
| Registration #7 | 2016-10-27 | 61.277 mi |
| Registration #8 | 2017-10-27 | 67.277 mi |
| Registration #9 | 2018-10-27 | 73.277 mi |
| Registration #10 | 2019-10-27 | 79.277 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 65 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Engine number | 92117C |