





report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Silver
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I



CarCheck.co.uk page 1/11



Internet history


Entry 1

Date 2021-10-07

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT	history
1.101	iliocol y

MOT expiry date	2023-12-06
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	7
Total items failed	2

MOT #10	2022-12-07 13:30
MOT test number	377826441316
Result	✓ Passed
Next expiry date	2023-12-06
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1)	

MOT #9	2021-11-19 15:53
MOT test number	351274417286
Result	✓ Passed
MOT #8	2021-02-05 09:41
MOT test number	998784610062
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7		2020-02-08 09:59
MOT test nu	mber	832910353721
Result		✓ Passed
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		

CarCheck.co.uk page 3/11



MOT #6 2020-02-08 09:59

MOT test number 812265844143

Result X Failed

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #5 2019-02-13 11:47

MOT test number 297160058893

Result ✓ Passed

MOT #4 2018-05-18 09:53

MOT test number 296064621206

Advice Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #3 2017-05-05 15:23

MOT test number 176767039343

Result

Passed

Advice Rear tyres have age related cracking

MOT #2 2016-05-23 12:42

MOT test number 513145595255

Result
✓ Passed

MOT #1 2015-06-30 14:33

MOT test number 658881185170

Result

Passed

Notice 1.advice o/s/f. tyre wearing on edge's.

CarCheck.co.uk page 4/11



Tax & MOT check



Tax expired: 10 February 2024

X MOT

Expired: 6 December 2023

Tax status	Expired at 10 February 2024
Days left	80 days too late
MOT expiry date	6 December 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		

	More info >	
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		,
Current registration	NK NK	
Plate since		
Current registration	NK NK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-06-29
Last registration	2022-12-07
Complete history	See info



Registration #1	2012-06-29	23 mi
Registration #2	2015-06-30	14.446 mi
Registration #3	2016-05-23	18.015 mi
Registration #4	2017-05-05	23.835 mi
Registration #5	2018-05-18	31.797 mi
Registration #6	2019-02-13	34.550 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles2Engine number1097033