



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S HDI
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-25
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT #16	2021-01-06 16:56
MOT test number	427043749136
Result	✓ Passed
Next expiry date	2022-01-05
Advice	Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))
Advice	Slight injector leak!
Minor	Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Minor	Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2019-06-21 09:28
MOT test number	867389485860
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))
Minor	Nearside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14	2018-06-29 13:29
MOT test number	891462957739
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Nail in tyre

MOT #13	2017-07-04 11:50
MOT test number	407976995716
Result	✓ Passed

**MOT #12** 2016-07-02 12:38**MOT test number** 434564985693**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2015-06-27 14:42**MOT test number** 555038775159**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #10** 2014-06-28 13:20**MOT test number** 299109374497**Result** ✓ Passed**MOT #9** 2013-07-01 11:29**MOT test number** 228492283420**Result** ✓ Passed**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #8** 2013-06-29 12:15**MOT test number** 247420783184**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

**MOT #7** 2012-06-30 11:25**MOT test number** 677642982199**Result** ✓ Passed**Notice** Nail in O/s rear tyre**Advice** Nearside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Notice** N/s rear seat belt is fraying**Notice** N/s rear tyre tread is wearing low and has a cut on the tread**MOT #6** 2011-06-27 12:46**MOT test number** 465368871187**Result** ✓ Passed**Notice** N/s rear seat belt is fraying in several places**Notice** Signs of gearbox oil leaking**Notice** Both front brake pads are wearing low**MOT #5** 2011-06-25 11:15**MOT test number** 185946971141**Result** ✗ Failed**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #4** 2010-07-06 16:51**MOT test number** 590427380189**Result** ✓ Passed**MOT #3** 2009-11-16 14:53**MOT test number** 182300429308**Result** ✓ Passed



MOT #2	2009-11-14 09:53
MOT test number	591858219309
Result	✗ Failed
Fail	Offside rear brake binding (3.7.B.1)
Pass with rectification	Nearside Headlamp aim too low (1.8)
Fail	Nearside rear brake binding (3.7.B.1)
Pass with rectification	Offside Headlamp aim too low (1.8)

MOT #1	2008-11-27 17:20
MOT test number	664082038324
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-11-30
Last registration	2021-01-06
Complete history	<a href="#">See info</a>



Registration #1	2005-11-30	24 mi
Registration #2	2008-11-27	27.250 mi
Registration #3	2009-11-14	33.485 mi
Registration #4	2009-11-16	33.522 mi
Registration #5	2010-07-06	38.265 mi
Registration #6	2011-06-25	46.024 mi
Registration #7	2011-06-27	46.312 mi
Registration #8	2012-06-30	54.596 mi
Registration #9	2013-06-29	63.024 mi
Registration #10	2013-06-29	63.024 mi
Registration #11	2013-06-29	63.024 mi
Registration #12	2013-06-29	63.024 mi
Registration #13	2013-06-29	63.024 mi
Registration #14	2013-06-29	63.024 mi
Registration #15	2013-06-29	63.024 mi
Registration #16	2013-06-29	63.024 mi
Registration #17	2013-06-29	63.024 mi
Registration #18	2013-06-29	63.024 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1306 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

JB390064134