





report date: 2024-03-28

### General information

Make	NISSAN
Model	LEAF ACENTA
Colour	Red
Year of manufacture	2017
Top speed	87 mph
Gearbox	1 speed automatic

# Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm at 10.500 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/12



ST67CDX report date: 2024-03-28

## Internet history

### Entry 2

Date	2021-07-01
Pictures	1
Listing price	View report



#### source: autoonline.co.uk

#### Entry 1

Date	2021-06-23	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

## MOT history

MOT expiry date	2024-07-04
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	21
Total items failed	4

MOT #7	2023-06-26 11:39
MOT test number	823643714730
Result	<b>✓</b> Passed
Next expiry date	2024-07-04
Advice O/s/f DRL not working	
Advice Offside Front Brake pipe corroded, covered in grease or other mater	rial (1.1.11 (c))
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice O/s/f fog light not working	
Advice Nearside Front Lower Suspension arm pin or bush worn but not result (5.3.4 (a) (i))	Ilting in excessive movement

MOT #6	2022-06-30 13:59
MOT test number	211247718461
Result	✓ Passed
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	n excessive movement
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	excessive movement
Advice O/s/f DRL not working	
Advice Tyre slightly damaged/cracking or perishing all tyres are cracking and peri	shing (5.2.3 (d) (ii))
Advice Offside Front Brake pipe corroded, covered in grease or other material cor	roding (1.1.11 (c))
Advice O/s/f fog light not working	

CarCheck.co.uk page 3/12



report date: 2024-03-28

✓ Passed

**MOT #5** 2022-06-30 07:59

**MOT test number** 505248853141

Result X Failed

**Advice** Offside Front Brake pipe corroded, covered in grease or other material corroding (1.1.11 (c))

Advice Tyre slightly damaged/cracking or perishing all tyres are cracking and perishing (5.2.3 (d) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice O/s/f DRL not working

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice O/s/f fog light not working

Result

MOT #4 2021-07-05 07:37

**MOT test number** 594505320502

Result \( \sqrt{Passed} \)

MOT #3 2021-06-30 13:58

**MOT test number** 764384105226

**Result** X Failed

**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #2** 2020-09-15 14:14

MOT test number 618560329501

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

CarCheck.co.uk page 5/12



report date: 2024-03-28

### Tax & MOT check





Tax status Expired at 26 April 2024

Days left 3 days too late

MOT expiry date 4 July 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

### Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	UK NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



ST67CDX report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-28
Last registration	2023-06-26
Complete history	See info



Registration #1	2017-09-28	18 mi
Registration #2	2020-09-14	18.582 mi
Registration #3	2020-09-15	18.583 mi
Registration #4		11.777 es
Registration #5	2021-06-30	21.102 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 66

More info >

CarCheck.co.uk page 11/12



ST67CDX report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2700 mm
Kerb weight	1538 kg
Max. allowed weight	1945 kg

## Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12