



OV08HVS

report date: 2024-03-28

General information

Make	NISSAN
Model	CABSTAR 35.13 SWB SHR PU 130
Colour	Red
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	270 Nm at 1.800 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2025-05-09
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	111
Total items failed	60

MOT #212024-04-10 15:54

MOT test number832601575856

Result✓ Passed

Next expiry date2025-05-09

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Non obligatory mirror damaged mirror glass cracked
- Advice** Nearside Front Upper Integral body structure is corroded but structural rigidity is not significantly reduced top of wheel arch has corrosion (6.1.1 (c) (i))
- Minor** Offside Front Obligatory mirror slightly damaged mirror glass cracked (3.3 (b) (i))
- Advice** Rear reverse lamp not working
- Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement bush slightly worn (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Upper Integral body structure is corroded but structural rigidity is not significantly reduced top of wheel arch has corrosion (6.1.1 (c) (i))
- Minor** Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources lamp broken (4.7.1 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement bush slightly worn (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #20**

2023-05-10 13:37

MOT test number

869768624334

Result

✓ Passed

- Advice** Offside Front Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security under wheel arch has corrosion (6.2.2 (d) (i))
- Advice** Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Non obligatory mirror damaged mirror cracked
- Minor** Offside Rear Registration plate lamp insecure registration lamp loose (4.7.1 (c) (i))
- Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both front anti roll bar D bushes slightly worn (5.3.4 (a) (i))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security under wheel arch has corrosion (6.2.2 (d) (i))
- Advice** Rear reverse lamp not working
- Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement anti roll bar D bush has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Obligatory mirror slightly damaged mirror cracked (3.3 (b) (i))
- Advice** Central Rear Prop shaft bearing has slight play (6.1.7 (b) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge inner tyre below limit (5.2.3 (e))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #19**

2023-04-27 15:51

MOT test number

723479041540

Result**✗ Failed****Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Horn not working (7.7 (a))**Advice** Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Offside Rear Anti-roll bar linkage pin or bush excessively worn anti roll bar O bushes excessively worn (on the end of the bar) (5.3.4 (a) (i))**Minor** Offside Rear Registration plate lamp insecure registration lamp loose (4.7.1 (c) (i))**Fail** Offside Rear Inner Tyre has ply or cords damaged inner wheel has hole in it (5.2.3 (d) (ii))**Advice** Nearside Front Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security under wheel arch has corrosion (6.2.2 (d) (i))**Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both front anti roll bar D bushes slightly worn (5.3.4 (a) (i))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement anti roll bar D bush has slight play (5.3.4 (a) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn bottom arm ball joint has excessive play (5.3.4 (a) (i))**Advice** Rear reverse lamp not working**Fail** Nearside Front Road wheel more than one fixing loose needs new wheel because the locator holes are excessively worn (5.2.1 (a) (ii))**Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Central Front Brake pedal has insufficient reserve travel (1.1.2 (a))**Fail** Offside Rear Lower Shock absorbers has an excessively worn bush bottom bush excessively worn (5.3.2 (c))**Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))**Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn anti roll bar O bushes excessively worn (on the end of the bar) (5.3.4 (a) (i))**Minor** Offside Front Obligatory mirror slightly damaged mirror cracked (3.3 (b) (i))

Advice Nearside Front Non obligatory mirror damaged mirror cracked

Advice Central Rear Prop shaft bearing has slight play (6.1.7 (b) (i))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge inner tyre below limit (5.2.3 (e))

Advice Offside Front Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security under wheel arch has corrosion (6.2.2 (d) (i))

Fail Nearside Front Lower Shock absorbers has an excessively worn bush bottom bush excessively worn (5.3.2 (c))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Battery insecure and likely to fall from carrier (4.13 (a) (ii))

Fail Nearside Rear Lower Shock absorbers has an excessively worn bush bottom bush excessively worn (5.3.2 (c))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Nearside Rear parking brake on calliper not working tidy

**MOT #18**

2022-03-09 14:39

MOT test number

175372326703

Result

✓ Passed

Minor Offside Rear Inner Tyre obviously under inflated inner wheel tyre flat (5.2.3 (l))**Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement
top arm rear bush has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre worn on outer edge (5.2.3 (e))**Minor** Offside Front Obligatory mirror slightly damaged mirror cracked (3.3 (b) (i))**Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement
top arm rear bush has slight play (5.3.4 (a) (i))**Advice** Central Front handbrake has little reserve travel**Minor** Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources lens
broken (4.7.1 (b) (i))

**MOT #17**

2022-03-01 17:18

MOT test number

981792557764

Result**✗ Failed**

- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Anti-roll bar pin or bush excessively worn d bushes have excess play (5.3.4 (a) (i))
- Fail** Offside Front Headlamp levelling device inoperative (4.1.5 (a))
- Minor** Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources lens broken (4.7.1 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement top arm rear bush has slight play (5.3.4 (a) (i))
- Minor** Offside Rear Inner Tyre obviously under inflated inner wheel tyre flat (5.2.3 (l))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Anti-roll bar pin or bush excessively worn d bushes have excess play (5.3.4 (a) (i))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Fail** Central Front Brake pedal has insufficient reserve travel (1.1.2 (a))
- Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement top arm rear bush has slight play (5.3.4 (a) (i))
- Minor** Offside Front Obligatory mirror slightly damaged mirror cracked (3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre worn on outer edge (5.2.3 (e))
- Fail** Rear Anti-roll bar linkage pin or bush excessively worn all 4 anti roll bar bushed have excess play 2x d bushes and 2x o bushes (5.3.4 (a) (i))
- Fail** Offside Front Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #16**

2021-03-11 13:50

MOT test number

333271001839

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #15

2019-08-02 15:44

MOT test number

644008343873

Result

✓ Passed

- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #14**

2019-07-24 13:13

MOT test number

202862713140

Result

✗ Failed

Fail Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Fail Offside Side repeater missing (4.4.1 (a) (ii))

Fail Nearside Front Electrical wiring connectors for braking disconnected pad (4.11 (a) (iii))

Fail Nearside Headlamp aim too far to the right (4.1.2 (a))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced wheel arch (7.1.1 (a) (i))

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

Fail Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Windscreen washer not working (3.5 (a))

Fail Offside Front Seat belt anchorage likely to become detached in the event of a collision wheel arch (7.1.1 (a) (ii))

MOT #13

2018-07-25 15:44

MOT test number

286228472900

Result

✓ Passed

Advice Offside Front step missing

Advice Rear mudguard brackets corroded



MOT #12	2018-07-09 14:27
MOT test number	651781161976
Result	✗ Failed
Fail	Nearside Side repeater missing (4.4.1 (a) (ii))
Fail	Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
Advice	Rear mudguard brackets corroded
Fail	Offside Side repeater not working (4.4.1 (a) (ii))
Advice	Offside Front step missing

MOT #11	2017-01-19 12:29
MOT test number	195957018517
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Non obligatory mirror damaged
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)
Advice	Offside step missing

**MOT #10**

2017-01-13 13:36

MOT test number

932682985118

Result**✗ Failed**

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside step missing
- Fail** Nearside Side repeater missing (1.4.A.2b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Non obligatory mirror damaged
- Fail** Windscreen wiper does not clear the windscreen effectively both (8.2.2)
- Fail** Offside Front Lower Shock absorber has an excessively worn bush (2.7.4)

MOT #9

2015-11-24 09:23

MOT test number

548327136830

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #8

2014-10-02 15:36

MOT test number

459735774274

Result**✓ Passed**

- Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Notice** Wear to rear anti-roll bar mounts.

**MOT #7**

2014-09-29 10:17

MOT test number

595322874285

Result**✗ Failed**

Fail Nearside Inner Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Fail Front registration plate deteriorated (6.3.1d)

Notice Both rear inner tyres flat.

Fail Offside Inner Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Stop lamp not working (1.2.1b)

Notice Wear to rear anti-roll bar mounts.

MOT #6

2013-07-23 16:52

MOT test number

948464303269

Result**✓ Passed**

Notice Both rear inner tyres flat

Notice O/s step missing

Notice N/s mirror damaged

Advice Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)

**MOT #5** 2013-07-17 14:04**MOT test number** 297598193490**Result** ✗ Failed

- Advice** Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Notice** Both rear inner tyres flat
- Fail** Front registration plate deteriorated (6.3.1d)
- Notice** N/s mirror damaged
- Fail** Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Lower Shock absorber has an excessively worn bush (2.7.4)
- Notice** O/s step missing
- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)
- Fail** Exhaust has a major leak of exhaust gases (7.1.2)

MOT #4 2012-07-04 16:39**MOT test number** 209406282489**Result** ✓ Passed

- Advice** Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Bodywork damage to cab of vehicle
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Notice** Front bumper insecure

**MOT #3** 2012-07-03 11:34**MOT test number** 617935382187**Result** ✗ Failed

- Notice** Front bumper insecure
- Fail** Direction indicators flashing more than 120 times a minute (1.4.A.2g)
- Advice** Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Side repeater missing (1.4.A.2b)
- Notice** Bodywork damage to cab of vehicle
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Side repeater missing (1.4.A.2b)

MOT #2 2011-06-01 14:14**MOT test number** 768902251149**Result** ✓ Passed

- Notice** Accident damage to offside front door step and bumper corner
- Advice** Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)



MOT #12011-05-31 10:51

MOT test number618341051197

Result		✗ Failed
Fail	Nearside Headlamp aim too high (1.8)	
Fail	Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)	
Notice	Accident damage to offside front door step and bumper corner	
Fail	Offside Headlamp aim too high (1.8)	
Advice	Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)	



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
9 May 2025

Tax status	Valid until 1 March
-------------------	---------------------

Days left	305
------------------	-----

MOT expiry date	9 May 2025
------------------------	------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-03-27
Last registration	2024-04-10
Complete history	See info



Registration #1	2008-03-27	24 mi
Registration #2	2011-05-31	20.254 mi
Registration #3	2011-06-01	20.260 mi
Registration #4	2012-07-03	25.297 mi
Registration #5	2012-07-04	25.298 mi
Registration #6	2013-07-17	29.859 mi
Registration #7	2013-07-23	29.864 mi
Registration #8	2014-09-29	33.429 mi
Registration #9	2014-10-02	33.446 mi
Registration #10	2015-11-24	37.352 mi
Registration #11	2017-01-13	38.724 mi
Registration #12	2019-05-29	39.377 mi
Registration #13	2019-05-29	39.377 mi
Registration #14	2019-05-29	39.377 mi
Registration #15	2019-05-29	39.377 mi
Registration #16	2019-05-29	39.377 mi
Registration #17	2019-05-29	39.377 mi
Registration #18	2019-05-29	39.377 mi
Registration #19	2019-05-29	39.377 mi
Registration #20	2019-05-29	39.377 mi
Registration #21	2019-05-29	39.377 mi
Registration #22	2019-05-29	39.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1900 mm
Kerb weight	1921 kg
Max. allowed weight	3500 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	897273