



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Black
Year of manufacture	2008
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-27
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-20
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #15	2023-12-21 09:30
MOT test number	175643251994
Result	✓ Passed
Next expiry date	2024-12-20

MOT #14	2022-10-17 14:04
MOT test number	250038094315
Result	✓ Passed
Advice	Nearside Front Steering rack has slight free play detected at steering wheel STEERING ARM INNER BALL JOINT (2.3 (a) (i))

MOT #13	2022-10-17 14:04
MOT test number	212651347836
Result	✗ Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Front Steering rack has slight free play detected at steering wheel STEERING ARM INNER BALL JOINT (2.3 (a) (i))
Pass with rectification	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #12** 2021-10-27 16:33**MOT test number** 648970979870**Result** ✓ Passed

- Advice** Front droplink gaiters deteriorated
- Advice** Offside front seat belt frayed
- Advice** Front lower suspension arm balljoint gaiters deteriorated

MOT #11 2020-11-17 15:00**MOT test number** 657324030325**Result** ✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10 2020-11-17 12:46**MOT test number** 833390769051**Result** ✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))

MOT #9 2019-05-28 09:33**MOT test number** 380462445316**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-05-17 10:09**MOT test number** 704024242500**Result** ✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

MOT #7 2017-05-22 08:25**MOT test number** 301140531660**Result** ✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

MOT #6 2016-05-20 12:25**MOT test number** 284119315350**Result** ✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)

MOT #5 2015-05-16 09:32**MOT test number** 186376535114**Result** ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

Advice Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

Notice Front console bushes starting to split



MOT #4	2014-05-17 11:47
MOT test number	385157534146
Result	✓ Passed
MOT #3	2013-05-15 14:54
MOT test number	605185733127
Result	✓ Passed
Advice	Offside Front Seat belt stitching slightly frayed (5.2.2b)
MOT #2	2012-05-12 09:27
MOT test number	616713332134
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Both rear tyres side walls cracking
MOT #1	2011-05-21 09:28
MOT test number	107351341131
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
20 December 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 HN08XZD
Plate since	2020-03-28
Current registration	 HN08XZD
Plate since	2020-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-05-24
Last registration	2023-12-21
Complete history	See info



Registration #1	2008-05-24	24 mi
Registration #2	2011-05-21	24.693 mi
Registration #3	2012-05-12	31.494 mi
Registration #4	2013-05-15	37.300 mi
Registration #5	2014-05-17	44.157 mi
Registration #6	2015-05-16	51.461 mi
Registration #7	2016-05-20	57.419 mi
Registration #8	2017-05-22	64.138 mi
Registration #9	2018-05-17	68.740 mi
Registration #10	2019-05-20	75.377 mi
Registration #11	2020-05-20	82.014 mi
Registration #12	2021-05-20	88.651 mi
Registration #13	2022-05-20	95.288 mi
Registration #14	2023-05-20	101.925 mi
Registration #15	2024-05-20	108.562 mi
Registration #16	2025-05-20	115.199 mi
Registration #17	2026-05-20	121.836 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 378141