




report date: 2024-03-28

General information

Make	VOLVO
Model	V50 SPORT V50
Colour	Blue
Year of manufacture	2006
Top speed	134 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	230 Nm at 4.400 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.2 mpg
Consumption extra urban	41.5 mpg
Consumption combined	30.7 mpg
CO2 emission	220 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-22
Pictures	14
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-04
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	19
Total items failed	7

MOT #20	2023-09-05 12:03
MOT test number	504690882318
Result	✓ Passed
Next expiry date	2024-09-04
Advice	Rear Lower Coil spring corroded both (5.3.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19	2022-09-01 16:21
MOT test number	709244847269
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

MOT #18	2022-08-30 14:00
MOT test number	657681792618
Result	✗ Failed
Advice	Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
Fail	Front Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17** 2021-08-20 16:40**MOT test number** 138937158272**Result** ✓ Passed**MOT #16** 2021-08-20 16:08**MOT test number** 358860686402**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #15** 2020-01-21 10:16**MOT test number** 833807635221**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14** 2019-01-31 16:52**MOT test number** 254854571575**Result** ✓ Passed**MOT #13** 2019-01-31 16:52**MOT test number** 647738601839**Result** ✗ Failed**Pass with rectification** Nearside Front Outline marker lamp not working (4.2.1 (a))**Pass with rectification** Offside Rear Outer Position lamp not working (4.2.1 (a))**MOT #12** 2018-03-06 11:02**MOT test number** 332299570099**Result** ✓ Passed**Advice** Nearside Front Tyre slightly worn inner and outer edges

**MOT #11** 2017-01-30 14:14**MOT test number** 734502236002**Result** ✓ Passed**MOT #10** 2016-02-03 09:27**MOT test number** 354858654509**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #9** 2016-02-03 09:27**MOT test number** 257613563101**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #8** 2015-02-09 12:33**MOT test number** 267780545059**Result** ✓ Passed**MOT #7** 2015-02-09 12:33**MOT test number** 509790445063**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2014-02-07 10:51**MOT test number** 168978334025**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-03-04 10:48**MOT test number** 176733163061**Result** ✓ Passed

Advice Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice Both rear & n/s/f tyres uneven wear

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2012-03-09 10:12**MOT test number** 767649362037**Result** ✓ Passed

Notice Offside front tyre inner edge bald

Advice Inner Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2011-03-30 16:55**MOT test number** 659059781062**Result** ✓ Passed**MOT #2** 2010-03-31 18:11**MOT test number** 542990490020**Result** ✓ Passed

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2009-03-25 16:54**MOT test number** 174474689055**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
4 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	4 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-20
Current registration	
Plate since	2019-06-20

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-31
Last registration	2023-09-05
Complete history	See info



Registration #1	2006-03-31	11 mi
Registration #2	2009-03-25	34.032 mi
Registration #3	2010-03-31	47.077 mi
Registration #4	2011-03-30	56.773 mi
Registration #5	2012-03-09	59.981 mi
Registration #6	2013-03-04	64.785 mi
Registration #7	2014-02-07	69.170 mi
Registration #8	2015-02-09	73.107 mi
Registration #9	2016-02-03	76.100 mi
Registration #10	2016-02-03	76.100 mi
Registration #11	2017-01-30	77.126 mi
Registration #12	2018-01-30	78.152 mi
Registration #13	2019-01-30	79.178 mi
Registration #14	2020-01-30	80.204 mi
Registration #15	2021-01-30	81.230 mi
Registration #16	2022-01-30	82.256 mi
Registration #17	2023-01-30	83.282 mi
Registration #18	2024-01-30	84.308 mi
Registration #19	2025-01-30	85.334 mi
Registration #20	2026-01-30	86.360 mi
Registration #21	2027-01-30	87.386 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1425 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	3958497