



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-07-24
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-23
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-15
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	23
Total items failed	10

MOT #13	2023-12-16 12:00
MOT test number	210171814786
Result	✓ Passed
Next expiry date	2024-12-15

MOT #12	2022-11-30 11:07
MOT test number	750985871244
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive movement Nearside & Offside (5.3.4 (a) (i))

MOT #11	2021-12-01 15:39
MOT test number	520707658336
Result	✓ Passed
Advice	Exhaust joints corroded

**MOT #10**

2021-08-23 15:24

MOT test number

404519511400

Result**✗ Failed**

- Advice** Offside Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #9

2020-10-19 13:52

MOT test number

310746263864

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2020-10-19 13:52**MOT test number** 487168476661**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2019-04-17 10:58**MOT test number** 264876552623**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2019-04-17 08:04**MOT test number** 440138101844**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2018-04-05 07:35**MOT test number** 107177324347**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Brake pad(s) wearing thin front and rear (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2018-04-04 06:13**MOT test number** 254885431356**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper not operating over a large enough area to give an adequate view linkage insecure (8.2.1c)**Advice** Brake pad(s) wearing thin front and rear (3.5.1g)**MOT #3** 2017-04-18 15:54**MOT test number** 828061234440**Result** ✓ Passed**MOT #2** 2016-04-15 09:43**MOT test number** 833867678172**Result** ✓ Passed**MOT #1** 2015-04-01 16:05**MOT test number** 787601995053**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
15 December 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	15 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DF12AJV
Plate since	2019-03-29
Current registration	 DF12AJV
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-04-19
Last registration	2023-12-16
Complete history	See info



Registration #1	2012-04-19	24 mi
Registration #2	2015-04-01	23.158 mi
Registration #3	2016-04-15	31.638 mi
Registration #4	2017-04-18	38.963 mi
Registration #5	2018-04-04	45.974 mi
Registration #6	2018-04-05	45.974 mi
Registration #7	2019-04-17	52.663 mi
Registration #8	2019-04-17	52.663 mi
Registration #9	2019-04-17	52.663 mi
Registration #10	2019-04-17	52.663 mi
Registration #11	2019-04-17	52.663 mi
Registration #12	2019-04-17	52.663 mi
Registration #13	2019-04-17	52.663 mi
Registration #14	2019-04-17	52.663 mi
Registration #15	2019-04-17	52.663 mi
Registration #16	2019-04-17	52.663 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1747 mm
Length	4576 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	145854K