





report date: 2024-03-29

### General information

Make	FIAT
Model	500 C MULTIJET LOUNGE
Colour	Red
Year of manufacture	2010
Top speed	112 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	95 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	85.6 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/13



## Internet history

### Entry 1

Date 2021-11-04

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-10-10
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	16
Total items failed	6

MOT #15		2023-10-11 10:03
MOT test nu	ımber	616126403681
Result		✓ Passed
Next expiry	date	2024-10-10
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Rear Bump Stop loose	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #14		2023-10-10 15:00
MOT test number		647624186318
Result		<b>≍</b> Failed
Fail Offside Front	Tyre has a bulge, caused by separation or partial failure o	of its structure (5.2.3 (d) (ii))
Advice Central Sto	op lamp(s) non-obligatory stop lamp not working (4.3.1 (a	n) (ii))
Advice Offside Rea	ar Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Rear Bump Stop loose		
Pass with rectificat	Offside Headlamp not working on dipped beam (4	.1.1 (a) (ii))
Advice Nearside R	Rear Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/13



Passed

MOT #13 2022-09-27 12:33

MOT test number 411481328761

**Result** ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

Result

**Advice** 

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2021-09-29 07:45

**MOT test number** 460226803539

MOT #11 2021-01-21 17:11

Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

**MOT test number** 847531482642

MOT #10 2020-05-05 08:19

**MOT test number** 321824040987

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #9 2019-04-09 15:18

**MOT test number** 192531169106

CarCheck.co.uk page 4/13



MOT #8 2019-04-08 08:31

MOT test number 776400418719

**Result** X Failed

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #7 2018-04-10 16:21

MOT test number 815910294562

**Result** ✓ Passed

MOT #6 2018-04-10 13:17

**MOT test number** 612547611263

Result X Failed

**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #5 2017-03-29 13:21

**MOT test number** 603249199926

Result 

Passed

MOT #4 2016-04-14 15:08

**MOT test number** 443498096618

**Result** 
✓ Passed

**Advice** Centre Stop light not working

MOT #3 2014-05-23 08:50

**MOT test number** 906222344121

**Result** 
✓ Passed

CarCheck.co.uk page 5/13



MOT #2 2013-05-24 17:24

**MOT test number** 225624243129

MOT #1 2013-05-24 11:47

**MOT test number** 567724243147

Result × Failed

**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



### Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	10 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
***************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK 312
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-21
Last registration	2023-10-11
Complete history	See info



Registration #1	2010-05-21	18 mi
Registration #2	2013-05-24	9.961 mi
Registration #3	2013-05-24	9.961 mi
Registration #4	2014-05-23	11.909 mi
Registration #5	2016-04-14	18.460 mi
Registration #6	2017-03-29	26.387 mi
Registration #7	2018-04-10	34.464 mi
Registration #8	2018-04-10	34.468 mi
Registration #9	2019-04-08	40.948 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		0.00 44
Registration #17		D.777 es

More info >

CarCheck.co.uk page 12/13



## Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Max. allowed weight	1420 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 13/13