



GU06MKE

report date: 2024-03-29

General information

Make	AUDI
Model	A4 T FSI S LINE
Colour	Black
Year of manufacture	2006
Top speed	144 mph
0 - 60 mph	8.1 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	200 BHP
Max. torque	279 Nm at 1.800 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	42.2 mpg
Consumption combined	33.2 mpg
CO2 emission	202 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-13
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-05-09
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	40
Total items failed	3

MOT #18	2024-04-12 06:59
MOT test number	827024791372
Result	✓ Passed
Next expiry date	2025-05-09

MOT #17	2023-04-15 08:13
MOT test number	879918301815
Result	✓ Passed

MOT #16	2022-04-30 11:25
MOT test number	927501994356
Result	✓ Passed

Advice Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))

MOT #15	2021-05-10 13:03
MOT test number	488250610891
Result	✓ Passed

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14**

2020-04-09 09:38

MOT test number

278613521162

Result

✓ Passed

Advice Nearside rear tyre has a slight cut in the outer side wall.**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #13**

2019-06-21 15:30

MOT test number

664862594288

Result

✓ Passed

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))



MOT #12 2018-06-27 14:38

MOT test number 792140644627

Result ✓ Passed

- Advice** Nearside Front Nail in tyre
- Advice** Offside Front tyre splitting on inner edge
- Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear tyre splitting on inner edge
- Minor** Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11 2018-06-27 14:38

MOT test number 455822645296

Result ✗ Failed

- Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Nail in tyre
- Advice** Nearside Rear tyre splitting on inner edge
- Minor** Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front tyre splitting on inner edge

**MOT #10** 2017-06-30 15:14**MOT test number** 680124382376**Result** ✓ Passed**Advice** Nearside Front Underfloor brace bar detached at rear**Advice** Nearside Rear Nail in tyre**MOT #9** 2016-06-28 16:21**MOT test number** 847525312917**Result** ✓ Passed**Advice** Nearside Front Underfloor brace bar, bolt missing/insecure**MOT #8** 2015-07-01 10:04**MOT test number** 386352085147**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #7** 2014-07-03 16:47**MOT test number** 377194784130**Result** ✓ Passed**MOT #6** 2014-07-03 12:43**MOT test number** 747324584196**Result** ✗ Failed**Fail** Rear fog lamp not working (1.3.2b)

**MOT #5** 2013-06-05 15:26**MOT test number** 747336153148**Result** ✓ Passed**MOT #4** 2012-06-06 16:31**MOT test number** 585028452139**Result** ✓ Passed**MOT #3** 2012-06-02 11:04**MOT test number** 276824852424**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #2** 2010-09-06 13:42**MOT test number** 864169040282**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2009-08-12 16:25**MOT test number** 472834729295**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
9 May 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	9 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-29
Current registration	
Plate since	2019-06-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-07-20
Last registration	2024-04-12
Complete history	See info



Registration #1	2006-07-20	28 mi
Registration #2	2009-08-12	16.911 mi
Registration #3	2010-09-06	28.326 mi
Registration #4	2012-06-02	32.212 mi
Registration #5	2012-06-06	32.212 mi
Registration #6	2013-06-05	49.285 mi
Registration #7	2014-07-03	57.046 mi
Registration #8	2014-07-03	57.046 mi
Registration #9	2015-07-01	59.311 mi
Registration #10	2016-06-28	61.604 mi
Registration #11	2016-06-28	61.604 mi
Registration #12	2016-06-28	61.604 mi
Registration #13	2016-06-28	61.604 mi
Registration #14	2016-06-28	61.604 mi
Registration #15	2016-06-28	61.604 mi
Registration #16	2016-06-28	61.604 mi
Registration #17	2016-06-28	61.604 mi
Registration #18	2016-06-28	61.604 mi
Registration #19	2016-06-28	61.604 mi
Registration #20	2016-06-28	61.604 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >


Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1777 mm
Height	1391 mm
Length	4573 mm
Wheel base	2650 mm
Max. allowed weight	2110 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	BWE 020331