



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Silver
Year of manufacture	2009
Top speed	147 mph
0 - 60 mph	9.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	207 g/km
CO2 label	K





Internet history

Entry 2

Date	2022-02-21
Pictures	15
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2022-02-19
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-07
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	17
Total items failed	8

MOT #17	2024-03-21 11:37
MOT test number	888567323808
Result	✓ Passed
Next expiry date	2025-04-07

MOT #16	2023-04-06 10:52
MOT test number	403806015872
Result	✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement upper arm (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement upper arm (5.3.4 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2023-03-28 08:32

**MOT test number**

285964230555

**Result****✗ Failed**

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement upper arm (5.3.4 (a) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement upper arm (5.3.4 (a) (i))

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2022-04-08 10:56

**MOT test number**

690408791925

**Result****✓ Passed****MOT #13**

2022-04-08 05:03

**MOT test number**

524857939781

**Result****✗ Failed**

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #12**

2021-10-28 13:31

**MOT test number**

592356901428

**Result****✓ Passed****MOT #11**

2020-09-03 15:32

**MOT test number**

231600063551

**Result****✓ Passed**



<b>MOT #10</b>	2019-09-12 16:03
----------------	------------------

<b>MOT test number</b>	489694674762
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #9</b>	2019-04-17 06:57
---------------	------------------

<b>MOT test number</b>	705791984763
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2018-06-29 15:32
---------------	------------------

<b>MOT test number</b>	361033885153
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2017-06-28 08:51
---------------	------------------

<b>MOT test number</b>	903292988817
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2016-06-28 11:43
---------------	------------------

<b>MOT test number</b>	998897599825
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2016-06-28 11:43
---------------	------------------

<b>MOT test number</b>	176112114554
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

- |                                |   |
|--------------------------------|---|
| <b>Pass with rectification</b> | Nearside Rear Direction indicators incorrect colour (1.4.A.2f)      |
| <b>Pass with rectification</b> | Nearside Front Headlamp aim too high (1.8)                          |
| <b>Pass with rectification</b> | Nearside Front Direction indicators incorrect colour (1.4.A.2f)     |
| <b>Pass with rectification</b> | Offside Front Headlamp aim too high and too far to the right. (1.8) |

**MOT #4** 2015-06-30 13:25**MOT test number** 678701985113**Result** ✓ Passed**Notice** Front tyres are beginning to perish on the outer side walls**MOT #3** 2014-06-04 16:51**MOT test number** 666185054166**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #2** 2013-06-11 11:56**MOT test number** 877572863180**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2012-06-18 10:55**MOT test number** 516070372119**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
27 April 2024

✓

MOT

Expires:  
7 April 2025

Tax status	Expired at 27 April 2024
Days left	2 days too late
MOT expiry date	7 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>LM09YSL</b>
Plate since	2024-03-28
Current registration	 <b>LM09YSL</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-06-29
Last registration	2024-03-21
Complete history	<a href="#">See info</a>



Registration #1	2009-06-29	28 mi
Registration #2	2012-06-18	51.185 mi
Registration #3	2013-06-11	53.979 mi
Registration #4	2014-06-04	56.589 mi
Registration #5	2015-06-30	59.010 mi
Registration #6	2016-06-28	61.836 mi
Registration #7	2016-06-28	61.836 mi
Registration #8	2017-06-28	64.479 mi
Registration #9	2018-06-29	67.397 mi
Registration #10	2019-04-17	69.683 mi
Registration #11	2020-06-29	71.377 mi
Registration #12	2021-06-29	73.377 mi
Registration #13	2022-06-29	75.377 mi
Registration #14	2023-06-29	77.377 mi
Registration #15	2024-03-21	79.377 mi
Registration #16	2024-03-21	81.377 mi
Registration #17	2024-03-21	83.377 mi
Registration #18	2024-03-21	85.377 mi
Registration #19	2024-03-21	87.377 mi
Registration #20	2024-03-21	89.377 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1540 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531147727