



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VIVARO 2900 L1H1 CDTi DCB SPORTIVE
Colour	Black
Year of manufacture	2016
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	46.3 mpg
CO2 emission	155 g/km
CO2 label	G





## MOT history

MOT expiry date	2024-05-27
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	13
Total items failed	4

## MOT #7 2023-05-03 13:45

MOT test number 578407229688

Result ✓ Passed

Next expiry date 2024-05-27

**Advice** Front Tyre worn close to legal limit/worn on edge o/s and n/s (5.2.3 (e))

**Advice** Rear brake back plates corroded

**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))

## MOT #6 2023-05-03 08:07

MOT test number 469181475584

Result ✗ Failed

**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))

**Advice** Front Tyre worn close to legal limit/worn on edge o/s and n/s (5.2.3 (e))

**Advice** Rear brake back plates corroded

**Fail** Rear Brake disc significantly and obviously worn inner faces, could not see brake pads (1.1.14 (a) (i))

**MOT #5** 2022-05-18 08:30**MOT test number** 644431932347**Result** ✓ Passed**Advice** Towbar component corroded, but not excessively (6.1.6 (a))**MOT #4** 2021-05-28 08:28**MOT test number** 640275775715**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s (1.1.14 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge o/s and n/s (5.2.3 (e))**MOT #3** 2021-05-26 12:33**MOT test number** 910043089626**Result** ✗ Failed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s (1.1.14 (a) (ii))**Fail** Front Windscreen washer not working (3.5 (a))**Fail** Rear Brake pad(s) less than 1.5 mm thick o/s and n/s (1.1.13 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge o/s and n/s (5.2.3 (e))**MOT #2** 2020-03-14 11:50**MOT test number** 625392200409**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2019-03-23 11:54**MOT test number** 444802451152**Result** ✓ Passed**Minor** Windscreen wiper blade defective both front (3.4 (b) (i))



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
27 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	27 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>CU16VGP</b>
Plate since	2019-09-29
Current registration	 <b>CU16VGP</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-03-31
Last registration	2023-05-03
Complete history	<a href="#">See info</a>



Registration #1	2016-03-31	24 mi
Registration #2	2019-03-23	82.501 mi
Registration #3	2020-03-14	112.448 mi
Registration #4	2021-05-26	122.322 mi
Registration #5	2022-05-26	151.277 mi
Registration #6	2022-05-26	151.277 mi
Registration #7	2022-05-26	151.277 mi
Registration #8	2023-05-03	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1770 kg
Max. allowed weight	2830 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	R9M MB - C067880LWU