



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 HDI ACTIVE
Colour	Silver
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	110 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-09-06
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-25
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	27
Total items failed	7

MOT #13	2023-09-26 12:04
MOT test number	293578747107
Result	✓ Passed
Next expiry date	2024-09-25
Advice	Chip in windscreen zone A
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))

MOT #12	2023-09-26 09:19
MOT test number	964355390590
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect bulb fitted incorrectly (4.1.2 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))
Advice	Chip in windscreen zone A
Fail	Offside Rear Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #11** 2022-09-21 11:22**MOT test number** 379900782812**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #10** 2022-09-21 11:22**MOT test number** 798044577557**Result** ✗ Failed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2021-09-06 15:55**MOT test number** 964153645786**Result** ✓ Passed**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2021-08-27 15:22**MOT test number** 898296942122**Result** ✗ Failed**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2020-11-27 09:49**MOT test number** 943476544286**Result** ✓ Passed**Advice** Exhaust mounting defective (6.1.2 (a))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #6** 2019-11-28 11:02**MOT test number** 260741609452**Result** ✓ Passed**MOT #5** 2018-11-20 10:02**MOT test number** 769502163717**Result** ✓ Passed**MOT #4** 2017-11-24 16:28**MOT test number** 819045485310**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2017-11-24 11:17**MOT test number** 772007320893**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Front Exhaust system not adequately supported (7.1.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2016-11-22 14:50**MOT test number** 842284817769**Result** ✓ Passed**Advice** Rear exhaust bracket rusted**Advice** Nearside front tyre on 2 mm**MOT #1** 2015-11-30 14:47**MOT test number** 898311765507**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
25 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	25 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>WU62VHD</b>
Plate since	2019-03-29
Current registration	<b>WU62VHD</b>
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-21
Last registration	2023-09-26
Complete history	<a href="#">See info</a>



Registration #1	2012-09-21	23 mi
Registration #2	2015-11-30	19.702 mi
Registration #3	2016-11-22	30.789 mi
Registration #4	2017-11-24	44.594 mi
Registration #5	2017-11-24	44.525 mi
Registration #6	2018-11-20	59.877 mi
Registration #7	2019-11-28	76.604 mi
Registration #8	2020-11-27	86.665 mi
Registration #9	2023-09-26	25,377 mi
Registration #10	2023-09-26	25,377 mi
Registration #11	2023-09-26	25,377 mi
Registration #12	2023-09-26	25,377 mi
Registration #13	2023-09-26	25,377 mi
Registration #14	2023-09-26	25,377 mi
Registration #15	2023-09-26	25,377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1815 mm
Height	1498 mm
Length	4276 mm
Wheel base	2608 mm
Kerb weight	1410 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	JBEE0158928