



SG07HCD

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG TDI SE 174PS DPF
Colour	Grey
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.0 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-12
Pictures	22
Listing price	View report



source: cargurus.co.uk

**MOT history****MOT #26** 2023-12-18 12:56**MOT test number** 720342179425**Result** ✗ Failed**Minor** Brake fluid warning lamp illuminated (1.1.10 (f))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Bonnet primary retaining device ineffective (3.1 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))**MOT #25** 2022-12-21 14:41**MOT test number** 700723230729**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #24** 2021-12-06 17:46**MOT test number** 348064555811**Result** ✓ Passed**MOT #23** 2021-12-06 11:23**MOT test number** 986988141633**Result** ✗ Failed**Advice** Offside Front wheel binding**DANGEROUS** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**DANGEROUS** Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**MOT #22**

2020-12-23 14:47

MOT test number

447562319656

Result

✓ Passed

- Advice** Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Play in steering rack inner joint(s) both
- Advice** Nearside Front fog light not working
- Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #21

2020-12-23 10:03

MOT test number

583577253195

Result

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Play in steering rack inner joint(s) both
- Advice** Nearside Front fog light not working
- Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #20

2019-05-17 12:48

MOT test number

511868690910

Result

✓ Passed

- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))



MOT #19

2018-04-26 14:17

MOT test number

770901732668

Result		✓ Passed
Advice	Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Oil leak	
Advice	Central Rear seat belt stork cover missing	
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice	Offside Front Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear tank strap corroded	

**MOT #18** 2018-04-24 09:14**MOT test number** 856796695418**Result** ✗ Failed**Advice** Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Offside Front Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Central Rear seat belt stork cover missing**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Lower coil spring broken (2.4.C.1a)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Rear tank strap corroded**Advice** Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Oil leak**Fail** Offside Front Lower coil spring broken (2.4.C.1a)**MOT #17** 2017-04-11 11:04**MOT test number** 579323145171**Result** ✓ Passed**MOT #16** 2016-04-12 13:55**MOT test number** 364449206705**Result** ✓ Passed

**MOT #15** 2016-03-04 12:28**MOT test number** 109482278463**Result** ✗ Failed**Fail** Driver's airbag obviously defective (5.4.1)**Pass with rectification** Offside Front position lamp(s) not working head light (1.1.A.3b)**Fail** Offside Front position lamp(s) not working side light (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #14** 2015-12-03 14:34**MOT test number** 902743756799**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #13** 2015-12-03 14:34**MOT test number** 239351328286**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Obligatory mirror seriously obscured affecting the rear view (8.1.2a)**Pass with rectification** Offside Front Driver's airbag obviously defective (5.4.1)**MOT #12** 2014-07-10 10:25**MOT test number** 676151394127**Result** ✓ Passed

**MOT #11** 2014-06-26 10:57**MOT test number** 428617274126**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Centre Rear Seat belt damaged but not affecting the operation of the belt (5.2.2a)**Notice** Front windscreen wipers slightly smearing screen**MOT #10** 2013-09-10 16:26**MOT test number** 867423353243**Result** ✗ Failed**Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** Front discs worn**MOT #9** 2013-08-07 10:19**MOT test number** 927029513206**Result** ✓ Passed**MOT #8** 2013-08-07 10:19**MOT test number** 698119813273**Result** ✗ Failed**Pass with rectification** Nearside Front All position lamps not working (1.1.A.3b)**MOT #7** 2013-06-20 16:38**MOT test number** 857731573116**Result** ✓ Passed**Notice** Offside rear brake disc corroded (outer).**Notice** Windscreen heavily scored in zone A from a previous worn wiper blade.**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #6** 2013-06-20 16:38**MOT test number** 285321073487**Result** ✗ Failed**Notice** Offside rear brake disc corroded (outer).**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Windscreen heavily scored in zone A from a previous worn wiper blade.**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #5** 2013-05-04 12:30**MOT test number** 886534923145**Result** ✗ Failed**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Rear coil spring cracked (2.4.C.1a)**MOT #4** 2011-06-06 16:01**MOT test number** 697537051142**Result** ✓ Passed**MOT #3** 2011-06-06 16:01**MOT test number** 165867651193**Result** ✗ Failed**Pass with rectification** Windscreen wiper not operating automatically when switched on (8.2.1b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2010-05-19 10:12**MOT test number** 612649430117**Result** ✓ Passed



MOT #1	2010-04-27 11:33
MOT test number	182817910199
Result	✗ Failed
Fail	Offside Registration plate lamp not working (1.1.5c)
Fail	Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SG07HCD
Plate since	2024-03-28
Current registration	 SG07HCD
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-03-12
Last registration	2023-12-18
Complete history	See info



Registration #1	2007-03-12	7 mi
Registration #2	2010-04-27	26.139 mi
Registration #3	2010-05-19	26.142 mi
Registration #4	2011-06-06	34.975 mi
Registration #5	2013-06-20	53.006 mi
Registration #6	2013-08-07	53.174 mi
Registration #7	2013-09-10	53.189 mi
Registration #8	2014-06-26	60.050 mi
Registration #9	2014-07-10	60.247 mi
Registration #10	2015-12-03	73.965 mi
Registration #11	2015-12-03	73.965 mi
Registration #12	2016-03-04	75.193 mi
Registration #13	2016-03-04	75.193 mi
Registration #14	2016-03-04	75.193 mi
Registration #15	2016-03-04	75.193 mi
Registration #16	2016-03-04	75.193 mi
Registration #17	2016-03-04	75.193 mi
Registration #18	2016-03-04	75.193 mi
Registration #19	2016-03-04	75.193 mi
Registration #20	2016-03-04	75.193 mi
Registration #21	2016-03-04	75.193 mi
Registration #22	2016-03-04	75.193 mi
Registration #23	2016-03-04	75.193 mi
Registration #24	2016-03-04	75.193 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1723 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2229 kg
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BPE 003437