





report date: 2024-03-29

General information

Make	MINI
Model	CLUBMAN JOHN COOPER WORKS
Colour	Grey
Year of manufacture	2017
Top speed	153 mph
0 - 60 mph	6.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	228 BHP
Max. torque	320 Nm at 1.250 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history


Entry 3

Date 2022-01-19

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2021-08-28
Pictures	3

Listing price <u>View report</u>







source: cargurus.co.uk

Entry 1

Date	2021-08-27
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-20
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	15
Total items failed	2

MOT #10		2024-01-17 16:12
MOT test	number	927021066988
Result		✓ Passed
Next expi	ry date	2025-01-20
Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm tread (5.2.3 (e))		
Advice (e))	Offside Rear Tyre worn close to legal limit/worn on edge 2mm tread very w	worn inner edge (5.2.3

MOT #9		2024-01-17 09:41
MOT test number	er	485322360384
Result		× Failed
Advice Offsid	le Rear Tyre worn close to legal limit/worn on edge 2mm tread ve	ery worn inner edge (5.2.3
MAJOR Nears inner edge (5.2.3	ide Rear Tyre has a cut in excess of the requirements deep enou	gh to reach the ply or cords
DANGEROUS wall (5.2.3 (d) (ii)	Offside Front Tyre has a bulge, caused by separation or partial f	ailure of its structure outer
Advice Nears	ide Front Tyre worn close to legal limit/worn on edge 3mm tread	(5.2.3 (e))
DANGEROUS wall (5.2.3 (d) (ii)	Nearside Rear Tyre has a bulge, caused by separation or partial)	failure of its structure outer
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5	.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2023-01-19 16:53 **MOT** test number 567345142692 Result ✓ Passed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2023-01-19 16:53 **MOT** test number 161441833407 Result **X** Failed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2022-01-21 10:48 985650360138 **MOT** test number Result Passed **MOT #5** 2022-01-21 10:48 **MOT** test number 525176224671 Result × Failed **Pass with rectification** Windscreen wiper missing Both sides (3.4 (a))

MOT #4 2021-09-27 08:54 **MOT** test number 811965108461 Result ✓ Passed Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/12



MOT #3	2021-02-12 10:24
MOT test number	518350817675
Result	✓ Passed
MOT #2	2020-02-13 16:35
MOT test number	547055407184
Result	✓ Passed
MOT #1	2020-01-11 13:39
MOT test number	304724112453
Result	✓ Passed

CarCheck.co.uk page 5/12





Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	20 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners die Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NIE.
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2017-09-26
Last registration	2024-01-17
Complete history	See info



Registration #1	2017-09-26	12 mi
Registration #2	2020-01-11	5.270 mi
Registration #3	2020-02-13	5.276 mi
Registration #4	2021-02-12	11.825 mi
Registration #5		11.177 es
Registration #6		11.777 es
Registration #7	2021-09-27	14.643 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3874 mm
Wheel base	2495 mm
Kerb weight	1280 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	44	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4 page 1	12/12

Number of axles 2

Engine number F656H547