



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI
Colour	Grey
Year of manufacture	2018
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-12-17
Pictures	18
Listing price	View report

□ □ □ □

source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-09
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	19
Total items failed	1

MOT #5	2023-11-15 08:51
--------	------------------

MOT test number	240174706971
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-12-09
------------------	------------

- Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Front Lower Suspension arm ball joint has slight play bolt on type (5.3.4 (a) (i))
- Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Vehicles internal headlight adjuster altered to recheck lights
- Advice

Nearside Rear Outer Road wheel slightly distorted (5.2.2 (c) (i))
- Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4** 2023-11-14 14:36**MOT test number** 879166608182**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Outer Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Lower Suspension arm ball joint has slight play bolt on type (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #3** 2022-12-10 17:02**MOT test number** 805884302390**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2021-12-06 16:45**MOT test number** 833004185206**Result** ✓ Passed**MOT #1** 2021-05-19 15:01**MOT test number** 268412118021**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 December 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	9 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-01-01
Current registration	 XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-06-30
Last registration	2023-11-15
Complete history	See info



Registration #1	2018-06-30	9 mi
Registration #2	2021-05-19	86.718 mi
Registration #3	2021-12-06	103.041 mi
Registration #4	2022-05-20	103.041 mi
Registration #5	2022-05-20	103.041 mi
Registration #6	2022-05-20	103.041 mi
Registration #7	2022-05-20	103.041 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1750 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M H4 - C158668LWZ