



report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO MYLIFE
Colour	Beige
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	15.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	166 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-10-30
Pictures	22
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-26
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	29
Total items failed	5

MOT #10	2023-10-26 13:16
MOT test number	398439022648
Result	✓ Passed
Next expiry date	2024-10-26
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear exhaust corroded
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #9	2023-10-21 11:00
MOT test number	358928690622
Result	✗ Failed
Fail	Windscreen washer not working (3.5 (a))
Fail	Offside Front Upper Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Nearside Side repeater not working (4.4.1 (a) (ii))
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear exhaust corroded
Minor	Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #8**

2022-10-27 09:57

**MOT test number**

783763739214

**Result**

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Rear exhaust corroded
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear seat laid flat not allowing inspection of seatbelts
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre

**MOT #7**

2022-10-26 14:03

**MOT test number**

975884242306

**Result**

✗ Failed

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Rear exhaust corroded
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear seat laid flat not allowing inspection of seatbelts
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #6** 2021-10-22 08:07**MOT test number** 355653265031**Result** ✓ Passed**MOT #5** 2020-11-19 09:53**MOT test number** 331260646942**Result** ✓ Passed**MOT #4** 2019-10-30 09:59**MOT test number** 545985874038**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing and wearing outer edge (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing and wearing outer edge (5.2.3 (d) (ii))**MOT #3** 2018-10-26 10:31**MOT test number** 161752319669**Result** ✓ Passed**MOT #2** 2017-11-24 09:12**MOT test number** 156992955858**Result** ✓ Passed**Advice** No rear seats at time of test**Advice** Nearside Rear Nail in tyre**Advice** Oil level low**MOT #1** 2016-06-16 08:56**MOT test number** 901581511162**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
26 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	26 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-06-18
Last registration	2023-10-26
Complete history	<a href="#">See info</a>



Registration #1	2013-06-18	20 mi
Registration #2	2016-06-16	9.500 mi
Registration #3	2017-11-24	13.060 mi
Registration #4	2018-10-26	15.622 mi
Registration #5	2019-10-30	18.379 mi
Registration #6	2020-11-19	19.605 mi
Registration #7	2021-05-20	20.277 mi
Registration #8	2021-05-20	20.277 mi
Registration #9	2021-05-20	20.277 mi
Registration #10	2021-05-20	20.277 mi
Registration #11	2021-05-20	20.277 mi
Registration #12	2023-10-26	20.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Wheel base	2755 mm
Kerb weight	1340 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1851010