



AVI20TL

report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Red
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 3

Date	2021-11-20
Pictures	39
Listing price	View report



source: yesauto.com

Entry 2

Date	2021-10-07
Pictures	40
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-06
Pictures	40
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-25
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #10	2023-11-22 14:49
MOT test number	413870174612
Result	✓ Passed
Next expiry date	2024-11-25
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #9	2022-11-21 14:45
MOT test number	372136682888
Result	✓ Passed

MOT #8	2021-11-26 17:00
MOT test number	329002848121
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7	2021-02-22 15:34
MOT test number	135812599324
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #6** 2020-02-20 11:42**MOT test number** 384289682587**Result** ✓ Passed**MOT #5** 2019-02-25 10:20**MOT test number** 722488792575**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2018-02-20 12:38**MOT test number** 840017478698**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2017-02-22 13:29**MOT test number** 628696276682**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2016-03-07 16:21**MOT test number** 700027506405**Result** ✓ Passed



MOT #1	2015-03-26 15:49
MOT test number	859475485014
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
25 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	25 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-04-14
Last registration	2023-11-22
Complete history	See info



Registration #1	2012-04-14	16 mi
Registration #2	2015-03-26	24.165 mi
Registration #3	2016-03-07	31.410 mi
Registration #4	2017-02-22	38.334 mi
Registration #5	2018-02-20	42.606 mi
Registration #6	2019-02-25	46.960 mi
Registration #7	2020-02-20	49.855 mi
Registration #8	2021-02-20	51.277 mi
Registration #9	2022-02-20	51.277 mi
Registration #10	2023-02-20	51.277 mi
Registration #11	2023-02-20	51.277 mi
Registration #12	2023-02-20	51.277 mi
Registration #13	2023-02-20	51.277 mi
Registration #14	2023-02-20	51.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2041867