





General information

Make	CITROEN
Model	C1 FEEL
Colour	Red
Year of manufacture	2016
Top speed	99 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	95 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	56.5 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	А








Internet history

Entry 1	
Date	2021-06-16
Pictures	10
Listing price	View report









source: autoonline.co.uk



MOT history

MOT expiry date	2025-05-10
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	17
Total items failed	1

MOT #8	2024-04-23 14:15
MOT test number	785061667338
Result	✓ Passed
Next expiry date	2025-05-10
Advice Nearside Front Lower Suspension arm pin or bush worn but not resultin (5.3.4 (a) (i))	ng in excessive movement
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting i (5.3.4 (a) (i))	n excessive movement
Advice Brake disc worn, pitted or scored, but not seriously weakened Both (1.3	1.14 (a) (ii))
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in (a) (i))	excessive movement (5.3.4

MOT #7	2024-04-23 14:15
MOT test number	724064959125
Result	🗙 Failed

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))





MOT #6		2023-05-11 14:02
MOT test	number	668322875090
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2022-05-10 11:2	29
MOT test	number 94674404785	50
Result	V Passe	ed
Advice (i))	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a)	
Advice	Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

MOT #4	2021-05-11 15:35
MOT test number	991543711600
Result	✓ Passed
MOT #3	2021-01-07 13:42

MOT test number	425594845099
Result	✓ Passed

MOT #2	2020-01-02 10:34
MOT test number	537612632319
Result	✓ Passed





MOT #1	2019-01-16 18:18
MOT test number	950984023170
Result	✓ Passed



Tax & MOT check

Tax due: 1 June 2024	✓ Taxed	Expires: 10 May 2025	✓ МОТ
Tax status			Valid until 1 June
Days left			33
MOT expiry date			10 May 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		48	
Band		А	

Band	А
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	Lamp
Туре	
Damage 2	VAMPL
Date	
Category	AMPL
Туре	

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-04-02
Last registration	2024-04-23
Complete history	See info



Registration #1	2016-04-02	8 mi
Registration #2	2019-01-16	31.512 mi
Registration #3	2020-01-02	38.777 mi
Registration #4	2021-01-07	43.614 mi
Registration #5	2021-05-11	45.520 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		10.000 est
Registration #9		11.777 mi

More info >





Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight	
Width	1615 mm
Height	1460 mm
Length	3465 mm
Wheel base	2340 mm
Kerb weight	855 kg
Max. allowed weight	1240 kg
Additional information	
Additional information Fuel tank capacity	35 l
	35 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 3